

Not Authorised
6/1 Rm @
Prermy After Paim
6 days

ESTIMATION REPORT

Vehicle No : SML2641U

 Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6, VF1RFA00462672926

Estimation No. : E23020007

Date : 13/02/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
Section: Remark						
1		ALLIANZ INSURANCE PTE LTD DOA: 10.02.2023 TP CLAIM	1.00	0.00	0.00	0.00
Subtotal						S\$ 0.00

Section: Parts						
2		901523953R TAILGATE OUTER PANEL GS4 (GARNISH)	1.00	844.69	0.00	844.69 7
3		901004631R TAILGATE ASSY	1.00	3,034.42	0.00	3,034.42 7
4		908895927R EMBLEM " DIAMOND "	1.00	218.83	0.00	218.83 7
5		908924456R LETTERING " RENAULT "	1.00	143.37	0.00	143.37 7
6		908923255R LETTING " SCENIC "	1.00	181.84	0.00	181.84 7
7		905700851R TAILGATE LOCK CATCHER	1.00	157.57	0.00	157.57 7
8		905031335R TAILGATE LOCK ASSY	1.00	154.30	0.00	154.30 7
9		265503413R REAR TAIL LAMP RH	1.00	602.37	0.00	602.37 7
10		265556150R REAR TAIL LAMP LH	1.00	602.37	0.00	602.37 7
11		265556011R REAR TAIL GATE LAMP LH	1.00	602.37	0.00	602.37 7
12		265503368R REAR TAILGATE LAMP RH	1.00	602.37	0.00	602.37 7
13		908309536R REAR TAIL GATE WEATHERSTIP	1.00	449.95	0.00	449.95 7
14		284422080R REVERSE CAMERA	1.00	961.51	0.00	961.51 7
15		848108783R TAILGATE OUTER PANEL MOULDING STRIP	1.00	634.50	0.00	634.50 7
16		791004963R REINFORCEMENT REAR PANEL	1.00	1,013.00	0.00	1,013.00 7

Continue on next page...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATION REPORT

Vehicle No : SML2641U
 Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6,VF1RFA00462672926

Estimation No. : E23020007
 Date : 13/02/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
17		849206563R REAR END PANEL INNER GARNISH	1.00	297.00	0.00 <i>PL</i>	297.00 <i>X</i>
18		622353354R SPARE TYRE PANEL	1.00	1,615.68	0.00 <i>CM</i>	1,615.68 <i>✓</i>
19		265853901R REAR BUMPER LOWER REFLECTOR LH/RH	1.00	467.10	0.00 <i>PL</i>	467.10 <i>X</i>
20		R850226425R BUMPER REAR	1.00	1,252.80	0.00 <i>PL</i>	1,252.80 <i>✓</i>
21		850189314R REAR BUMPER PAD LOWER (BLACK)	1.00	749.65	<i>MY</i> 0.00 <i>CM</i>	749.65 <i>✓</i>
22		850703057R REAR BUMPER LOWER (SIVER)	1.00	652.32	0.00 <i>PL</i>	652.32 <i>✓</i>
23		756100714R REAR BUMPER REINFORCEMENT	1.00	862.92	0.00	862.92 <i>7</i>
24		850476580R REAR BUMPER LOWER PAD SUPPORT CTE	1.00	109.62	0.00	109.62 <i>7</i>
25		850471325R REAR BUMPER LOWER SUPPORT LH	1.00	143.10	0.00	143.10 <i>7</i>
26		850465793R REAR BUMPER LOWER SUPPORT RH	1.00	143.10	0.00	143.10 <i>7</i>
27		850429618R REAR BUMPER CENTER GARNISH	1.00	449.55	0.00	449.55 <i>7</i>
28		REAR BUMPER ANTENNA , ELECTRICAL	1.00	94.50	0.00	94.50 <i>7</i>
29		240154998R REAR BUMPER SENSOR HARNESS	1.00	260.82	0.00	260.82 <i>7</i>
30		253A44101R REAR REVERSE SENSOR	<i>3</i> 1.00	328.00	0.00 <i>PL</i>	1,312.00 <i>LHT</i>
31		284389618R BLIND SPOT SENSOR	2.00	515.43	0.00 <i>PL</i>	1,030.86 <i>X</i>
32		908B86823R RIVET FIX P	6.00	11.34	0.00 <i>PL</i>	68.04 <i>✓</i>
33		7703072047 RIVET SILVER	9.45	10.00	0.00 <i>PL</i>	94.50 <i>✓</i>

Continue on next page...

ESTIMATION REPORT

Vehicle No : SML2641U
 Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6,VF1RFA00462672926

Estimation No. : E23020007
 Date : 13/02/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
Subtotal						S\$ 19,807.02

Section: Special nett

34		REAR BUMPER CLIPS	6.00	7.00	0.00	42.00 ✓
35		REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER SET	1.00	35.00	0.00	35.00 ✓
36		REAR TYRE PANAL SEALANT	1.00	35.00	0.00	35.00 ✓
37		REAR END PANEL SEALANT	1.00	35.00	0.00	35.00 ?
38		REAR TAIL GATE OUTER GARNISH CLIPS SET	10.00	7.00	0.00	70.00 X
39		REAR TAIL GATE TRIM CLIP	6.00	7.00	0.00	42.00 X
40		REAR NUMBER PLATE WITH CASING	1.00	35.00	0.00	35.00 ✓
Subtotal						S\$ 294.00

Section: Labour

41		TO PANAL BEATING , REALIGN DISMANTLE REAR BUMPER , REAR BOOT LID, END PANEL OUTER, AND ALL NECESSARY ETC	1.00	1,500.00	0.00	1,500.00 700
42		TO CHECK ELECTRICAL WIRING SYSTEM OF REAR SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF REAR TAILL GATE LAMP & TAIL LAMP LH/RH	1.00	120.00	0.00	120.00 201
43		TO DISMAITE & RENEW REVERSE SENSOR	1.00	120.00	0.00	120.00 601
44		TO REMOVE AND REFIX REVERSE SENSOR WIRE HARDESS	1.00	120.00	0.00	120.00 ?

Continue on next page...

ESTIMATION REPORT

Vehicle No : SML2641U
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6,VF1RFA00462672926

Estimation No. : E23020007

Date : 13/02/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
45		TO REMOVE & INSTALL LUGGAGE COMPARTMENT AND SIDE FENDER INNER TRIM TO ACILITATE REPAIR	1.00	120.00	0.00	120.00
46		TO TEST WATER SEEPAGE REAR SCREEN & SUNROOF WATER LEAKAGE	1.00	80.00	0.00	80.00
47		TO REMOVE AND REFIT REAR WINDSCREEN	1.00	120.00	0.00	120.00
48		TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	120.00	0.00	120.00
49		TO PUTTY & RESPRAY PAINTING REAR BUMPER ,REAR BOOT LID, END PANAL, CHASSIS LH/RH AND ALL NECESSARY ETC	1.00	1,300.00	0.00	1,300.00

Subtotal S\$ 3,600.00

Remarks:

ALLIANZ INSURANCE PTE LTD

DOA: 10.02.2023

TP CLAIM

Remark Subtotal	S\$ 0.00
Parts Subtotal	S\$ 19,807.02
Special nett Subtotal	S\$ 294.00
Labour Subtotal	S\$ 3,600.00
Total Discount	S\$ 0.00