



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|---|--|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: ANG YVONNE | | | Ref: CS/HSB23001562/Kqp3m4 Date: 16/03/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHC 7798A | Veh. Inspected | SLQ 351E | |
| Policy No. | VFX/P2419140 | Coverage (\$) | 0.00 | |
| Claim No. | S3M04J9P | Excess (\$) | 0.00 | |
| Assign From | ANG YVONNE | Assign Date | 13/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | KIA CERATO K3 (A) | c.c | 1591 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | KNAFX411MJ5724978 | Colour | WHITE | |
| Odometer | 85825 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| L/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| R/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| L/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 11/02/2023 | Inspection Date | 23/02/2023 | |
| Survey held at | AUTO INSURE PTE LTD 6 MARSILING LANE S739145 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |