Huey Yon (LKKAuto)

From: Edward Lim (LKK Auto)

Sent: Monday, 27 February 2023 12:57 PM

To: Huey Yon (LKKAuto)

Subject: Fw: REQUEST SUPPLEMENTARY _ SLZ6701S DESKTOP SURVEY

Huey Yon,

Workshop has confirmed repair cost.

Best Regards,

Edward Lim | Asst. Automotive Assessor LKK Auto Consultants Pte. Ltd

Phone: 6256 3561 | Email: EdwardLim@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Leong Chee Kwong <cheekwong.leong@premierauto.com.sg>

Sent: Monday, February 27, 2023 11:57 AM

To: Edward Lim (LKK Auto) <edwardlim@lkkauto.com>

Subject: RE: REQUEST SUPPLEMENTARY _ SLZ6701S DESKTOP SURVEY

Dear Edward,

We confirmed COR 3193.80 with 5 days of repair

Thanks

From: Edward Lim (LKK Auto) <edwardlim@lkkauto.com>

Sent: Monday, 27 February 2023 9:30 AM

To: Leong Chee Kwong <cheekwong.leong@premierauto.com.sg> **Subject:** Re: REQUEST SUPPLEMENTARY _ SLZ6701S DESKTOP SURVEY

Mr. Leong,

Please see correction below.

Best Regards,

Edward Lim | Asst. Automotive Assessor

LKK Auto Consultants Pte. Ltd

Phone: 6256 3561 | Email: EdwardLim@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Edward Lim (LKK Auto)

Sent: Monday, February 27, 2023 9:18 AM

To: Leong Chee Kwong < cheekwong.leong@premierauto.com.sg **Subject:** RE: REQUEST SUPPLEMENTARY _ SLZ6701S DESKTOP SURVEY

Mr. Leong, Without prejudice

We will be advising our principal a cost of repair of Lum Sum \$3193.80 with 5 days of repair, subject to their approval.

Best Regards,

Edward Lim | Asst. Automotive Assessor LKK Auto Consultants Pte. Ltd

Phone: 6256 3561 | Email: EdwardLim@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)