

ASS. REC. BY:

REF:

CS/ICS23001618/Rgy3

5954

C08-2631/100

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMU 2036Uat Workshop m/s WAT HONHof TOT HONH AND ESSIInsured: ECICS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: waived

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 99K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 2036U Yr Regn: 2011 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 523I 2.5 ATARS c.c. 2497Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 182015 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WHA PP 32050C 866 728Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt or _____Brake: Order / Jammed / Leaked / Burnt or _____Modl: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 245/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/02/23 D.O.I. 14/02/23Survey held at WAT HONHDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT-60K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Other _____

Report Format: _____

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER:

ECGS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1706
Policy No:	MPO22B001519970	Date of Loss:	10/02/2023
Vehicle Reg. No.:	SNU220001	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ARVIN KUMAR S/O RAM SANKAR		

Make/Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	15/06/2011
Vehicle Colour:	BLUE		
Engine No:	05997785N52B25AF	Chassis No:	WBAFP32050C866728
Odometer:	182013 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	11,910.00
Miscellaneous Items	115.00
Labour	2,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	14,355.00
+ GST 8.00% (\$\$)	1,148.40
Nett Amount (\$\$)	15,503.40

This claim is handled by: THONG ZHONGMING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2023)
Parts:	143	BMW 523i 2.5 AT ABS D173 2WD 412 CLASSIC NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Wah Hong Motors & Credit Pte Ltd/SMU2036U/13/02/2023 17:52	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>bu</i> ✓	0.00	0.00	*2,500.00 F
2	1		*Bonnet insulator <i>de</i> ✓	0.00	0.00	*260.00 F
3	1		*Bonnet hinges assy LH/RH @2*\$120 X	0.00	0.00	*240.00 F
4	1		*Bonnet damper assy LH/RH @2*\$120 X	0.00	0.00	*240.00 F
5	1		*Bonnet lock assy LH/RH @2*\$200 <i>bt</i> ✓	0.00	0.00	*400.00 F
6	1		*Bonnet rubber strip outer <i>cut</i> ✓	0.00	0.00	*60.00 F
7	1		*Bonnet rubber strip inner <i>cut</i> ✓	0.00	0.00	*60.00 F
8	1		*Front fender top garnish LH/RH @2*\$270 <i>cut</i> ✓	0.00	0.00	*540.00 F
9	1		*Front bumper <i>de</i> ✓	0.00	0.00	*1,450.00 F
10	1		*Front bumper side retainer LH/RH @2*\$40 ?	0.00	0.00	*80.00 F
11	1		*Front bumper sponge <i>cut</i> ✓	0.00	0.00	*100.00 F
12	1		*Front reinforcement beam <i>bt</i> ✓	0.00	0.00	*750.00 F
13	1		*Front bumper nozzle cover LH/RH @2*\$55 <i>LH cut / ipl</i>	0.00	0.00	*110.00 F
14	1		*Front bumper nozzle cover bracket LH/RH @2*\$18 <i>LH-? / RH-X (ipl)</i>	0.00	0.00	*36.00 F
15	1		*Front bumper lower grille LH/RH @2*\$115 <i>RH cut / LH-MIS</i>	0.00	0.00	*230.00 F
16	1		*Front bumper lower Center grille LH/RH @2*\$95 <i>MIS</i> ✓	0.00	0.00	*190.00 F
17	1		*Front bumper lower grille garnish LH/RH @2*\$40 <i>MIS</i> ✓	0.00	0.00	*80.00 F
18	1		*Center grille LH/RH @2*\$160 <i>cut</i> ✓	0.00	0.00	*480.00 F
19	1		*Radiator top panel <i>bt</i> ✓	0.00	0.00	*50.00 F
20	1		*Front air duct lower ?	0.00	0.00	*60.00 F
21	1		*Front air duct ?	0.00	0.00	*650.00 F
22	1		*Condenser ?	0.00	0.00	*720.00 F
23	1		*Radiation ?	0.00	0.00	*1,150.00 F
24	1		*Fan cowling ?	0.00	0.00	*430.00 F
25	1		*Fog lamp LH/RH @2*\$260 X	0.00	0.00	*520.00 F
26	1		*Condensor Front Support beam LH/RH @2*\$250 ?	0.00	0.00	*500.00 F
27	1		*Radiator top panel clip male 2*\$4 <i>cut</i> ✓	0.00	0.00	*8.00 F
28	1		*Radiator top panel clip female 2*\$8 <i>cut</i> ✓	0.00	0.00	*16.00 F
29	1		*Front Door LH (Repair refer to the labor)	0.00	0.00	*- F
30	1		*Front fender LH/RH (Repair refer to the labor)	0.00	0.00	*- F

=Franchise part.

Total Parts (\$\$)

11,910.00

Wah Hong Motors & Credit Pte Ltd/SMU2036U/13/02/2023 17:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	Center Grille clips <i>new</i>	
2	1	Coolant <i>new</i>	30.00
3	1	Front bumper Clips <i>new</i>	50.00
			35.00
Sub Total (S\$)			115.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	600	1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800	1,200.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New		30.00
4	Remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New		100.00
Gross Labour Cost (S\$)				2,330.00

Wah Hong Motors & Credit Pte Ltd/SMU2036U/13/02/2023 17:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
6 days
43
14/02/23 @ 1630
EXCESS - WAIVED
Revert
Resy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	595G
Vehicle Details	
Vehicle No.:	SMU2036U
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2023
Vehicle Make:	BMW
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	05997785N52B25AF
Chassis No.:	WBAFP32050C866728
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$44,497.00
Original Registration Date:	15 Jun 2011
First Registration Date:	15 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$44,497.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2031
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$47,316.00
COE Rebate Amount:	\$38,851.00
Total Rebate Amount:	\$38,851.00

BMW 5 Series 523i (COE till 09/2031)

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$105,800** (3.75% loan with \$500 cash back.) [Get Pre-approved Loan.](#)

Depreciation ⓘ \$12,260 /yr

Reg Date 30-Sep-2011
(8yrs 7mths 15days COE left)

Mileage N.A.

Manufactured ⓘ 2011

Road Tax ⓘ \$2,155 /yr

Transmission Auto

Dereg Value ⓘ \$50,146 as of today ([change](#))

OMV ⓘ \$48,780

COE ⓘ \$58,124

ARF ⓘ \$48,780

Engine Cap 2,497 cc

Power 150.0 kW (201 bhp)

Curb Weight ⓘ 1,650 kg

No. of Owners ⓘ 5

Type of Vehicle [Luxury Sedan](#)