

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Feb 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3537H/13/02/2023 11:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR ASSY LH <i>Scr R</i>	20.00	0.00	*2,147.90 FL*
2	1		*REAR WHEEL RIM CAP LH <i>Scr</i>	20.00	0.00	*346.40 FL
3	1		*REAR DOOR COMFORT APPS LOGO <i>Nec</i>	0.00	0.00	*75.00 F
4	1		*REAR PATROL STICKER <i>Nec</i>	0.00	0.00	*30.00 F
Sub Total (\$\$)						2,599.30
- List Item Discount on L Items (\$\$)						498.86
Total Parts (\$\$)						2,100.44

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/02/2023 11:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$$T = 346.40$$

$$20\% = 69.28$$

$$T = 277.12$$

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	800.00 ⁷⁰⁰
2	SPARYPAINT	New	750 800.00 500
3	TRANSFER DOOR PARTS	New	120.00 ^{X 140}
Gross Labour Cost (S\$)			1,720.00

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/02/2023 11:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

T= 1843.12

2 days

14/2 P/P

14/2/23

2pm

11pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: