

Scan ✓

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **GBL 6380B**
Made : Nissan
Model : NV350 Caravan DX
Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Panel	1	\$ 1,426.70	\$ 1,426.70
2	Front Bumper	1	\$ 634.50	\$ 634.50
3	Front Bumper Fog Lamp Garnish RH	1	\$ 187.00	\$ 187.00
4	Front Bumper Side Retainer RH	1	\$ 186.00	\$ 186.00
5	Front Bumper Side Retainer LH	1	\$ 186.00	\$ 186.00
6	Front Bumper Reinforcement	1	\$ 762.00	\$ 762.00
7	Front Grille Assembly	1	\$ 676.20	\$ 676.20
8	Front Grille Emblem	1	\$ 79.90	\$ 79.90
9	Front Headlamp Assembly RH	1	\$ 685.90	\$ 685.90
10	Front Headlamp Assembly LH	1	\$ 685.90	\$ 685.90
11	Front Corner Panel RH	1	\$ 597.70	\$ 597.70
12	Front Door Side Mirror Assembly RH	1	\$ 616.80	\$ 616.80
13	Front Door Side Mirror Cover RH	1	\$ 148.00	\$ 148.00
14	Front Door RH	1	\$ 2,540.30	\$ 2,540.30
15	Front Door Upper Hinge RH	1	\$ 58.00	\$ 58.00
16	Front Door Lower Hinge RH	1	\$ 58.00	\$ 58.00
17	Front Door Checker RH	1	\$ 74.50	\$ 74.50
18	Front Door Rubber Seal RH	1	\$ 73.20	\$ 73.20
19	Front Door Lock RH	1	\$ 289.30	\$ 289.30
20	Front Door Lock Catch RH	1	\$ 58.10	\$ 58.10
21	Front Door Lower Rubber Seal RH	1	\$ 93.70	\$ 93.70
22	Front Door Glass Regulator RH	1	\$ 317.20	\$ 317.20
23	Front Door Glass Regulator Motor RH	1	\$ 537.30	\$ 537.30
24	Front Door Back Panel RH	1	\$ 736.10	\$ 736.10
25	Front Step Garnish RH	1	\$ 277.40	\$ 277.40
26	Front Wheel Rim RH	1	\$ 317.10	\$ 317.10
27	Front Wheel Rim Cap RH	1	\$ 160.00	\$ 160.00
28	Front Wheel Bearing RH	1	\$ 452.00	\$ 452.00
29	Front Shock Absorber RH	1	\$ 184.50	\$ 184.50
30	Front Lower Arm RH	1	\$ 284.50	\$ 284.50
31	Front Knuckle Arm RH	1	\$ 459.20	\$ 459.20
32	Front Upper Arm RH	1	\$ 350.00	\$ 350.00

33	Front Lower Arm Ball Joint RH	X	1	\$	98.00	\$	98.00
34	Sliding Door RH	X	1	\$	2,032.70	\$	2,032.70
35	Sliding Door Inner Trim Board RH	X	1	\$	458.40	\$	458.40
36	Sliding Door Weatherstrip RH	X	1	\$	156.30	\$	156.30
37	Sliding Door Outer Handle RH	X	1	\$	194.00	\$	194.00
38	Sliding Door Lower Hinge RH	X	1	\$	211.40	\$	211.40
39	Sliding Door Lower Hinge Roller RH	X	1	\$	167.20	\$	167.20
40	Sliding Door Centre Railing RH	X	1	\$	505.90	\$	505.90
41	Sliding Door Centre Railing Garnish RH	X	1	\$	384.50	\$	384.50
42	Sliding Door Centre Railing Garnish Side Cover RH	X	1	\$	132.00	\$	132.00
43	Sliding Door Lock RH	X	1	\$	328.30	\$	328.30
44	Sliding Door Lock Catch RH	X	1	\$	23.90	\$	23.90
45	Rear Side Panel RH	Dent	1	\$	2,164.20	\$	2,164.20
46	Rear Wheel Rim RH	Scr X	1	\$	317.10	\$	317.10
47	Rear Wheel Rim Cap RH	Scr	1	\$	160.00	\$	160.00
48	Rear Shock Absorber RH	X	1	\$	128.90	\$	128.90
49	Rear Wheel Bearing RH	X	1	\$	321.00	\$	321.00
50	Rear Axle Shaft RH	X	1	\$	458.00	\$	458.00
51	Rear Axle Housing	X	1	\$	1,683.60	\$	1,683.60
52	Rear Axle Housing Shaft Oil Seal	X	1	\$	64.00	\$	64.00
53	Rear Bumper	Scr / Bcr	1	\$	722.00	\$	722.00
54	Rear Bumper Side Retainer RH	X	1	\$	73.50	\$	73.50
55	Rear Bumper Side Retainer LH	X	1	\$	73.50	\$	73.50
56	Rear Taillamp Assembly RH	X	1	\$	409.30	\$	409.30

Parts Sub Total : \$ 25,460.70

10% Discount \$ 2,546.07

PARTS TOTAL : \$ 22,914.63

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate X	1	\$ 50.00	\$ 50.00
2	Front Bumper Clips - Set X	1	\$ 50.00	\$ 50.00
3	Front Grille Clips - Set X	1	\$ 50.00	\$ 50.00
4	Front Door Inner Trim Board RH Clips - Set X	1	\$ 50.00	\$ 50.00
5	Sliding Door Inner Trim Board RH Clips - Set X	1	\$ 50.00	\$ 50.00
6	Rear Bumper Clips - Set Vec ✓	1	\$ 50.00	\$ 50.00
7	Sliding Door Glass Sealant RH X	1	\$ 150.00	\$ 150.00
8	Rear Side Panel Glass Sealant RH X	1	\$ 150.00	\$ 150.00
9	Rear Tailgate Windscreen Glass Sealant X	1	\$ 150.00	\$ 150.00
10	Front Panel Sealant X	1	\$ 150.00	\$ 150.00
11	Front Door RH Sealant X	1	\$ 150.00	\$ 150.00
12	Front Door Back Panel RH Sealant X	1	\$ 150.00	\$ 150.00
13	Sliding Door RH Sealant X	1	\$ 150.00	\$ 150.00
14	Rear Side Panel RH Sealant 60	1	\$ 250.00	\$ 250.00
15	Front Door Company Sticker RH X	1	\$ 150.00	\$ 150.00
16	Front Tyre RH X	1	\$ 250.00	\$ 250.00

17	Rear Tyre RH X	1	\$ 250.00	\$ 250.00
18	Rear Axle Gear Oil (3L) X	1	\$ 120.00	\$ 120.00
SPECIAL NETT TOTAL :				\$ 2,370.00

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 400	2,600.00
2	To Spray Paint Affected Areas	\$ 400	2,200.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Remove & Refix Rear Side Panel RH Glass	\$ X	150.00
5	To Remove & Refix Sliding Door RH Glass	\$ X	150.00
6	To Transfer Sliding Door RH Mechanism	\$ X	150.00
7	To Transfer Front Door RH Mechanism	\$ X	150.00
8	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X	150.00
9	To Remove & Refix Front Undercarriage	\$ X	350.00
10	To Remove & Refix Rear Undercarriage	\$ X	500.00
11	To Conduct Four Wheel Alignment	\$ X	150.00
12	To Remove & Refix Front and Rear Tyre and Conduct Wheel Balancing	\$ X	150.00
13	To Remove & Refix and Adjust Rear Axle Gears to facilitate repairs	\$ X	450.00
14	To Remove & Refix Rear Bumper Reverse Sensors	\$ 30	150.00
15	To apply anti rust on affected parts	\$ 40	150.00
16	To Conduct Water Leak Test	\$ X	100.00
17	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
LABOUR TOTAL :		\$	8,130.00

4 days

L/S

10km 15/2/23

S

PARTS TOTAL : \$ 22,914.63
SPECIAL NETT TOTAL : \$ 2,370.00
LABOUR TOTAL : \$ 8,130.00
GRAND TOTAL : \$ 33,414.63

520pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: