





# REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 21 Feb 2023)

Parts: N/A TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE9009S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

GBE9009S  
TP/CHINA

## Estimates on Parts

| No. | Qty | Part No. | Particulars                        | %Disc | %Depr | Amount      |
|-----|-----|----------|------------------------------------|-------|-------|-------------|
| 1   | 1   |          | *1 PC FRT PANEL                    | 0.00  | 0.00  | *340.00 F   |
| 2   | 1   |          | *1 PC FRT PANEL EMBLEM (DYNA)      | 0.00  | 0.00  | *30.00 F    |
| 3   | 1   |          | *1 PC FRT WINDSCREEN GLASS RUBBER  | 0.00  | 0.00  | *95.00 F    |
| 4   | 1   |          | *1 PC FRT RH CORNAL PANEL          | 0.00  | 0.00  | *85.00 F    |
| 5   | 1   |          | *1 PC FRT PANEL CENTRE TOP GARNISH | 0.00  | 0.00  | *125.00 F   |
| 6   | 1   |          | *1 PC RH CENTRE TOP GARNISH        | 0.00  | 0.00  | *50.00 F    |
| 7   | 1   |          | *1 PC FRT GRILLE                   | 0.00  | 0.00  | *180.00 F   |
| 8   | 1   |          | *1 PC FRT GRILLE LOGO              | 0.00  | 0.00  | *35.00 F    |
| 9   | 1   |          | *1 PC AIR-CON EVAPORATOR           | 0.00  | 0.00  | *1,050.00 F |
| 10  | 1   |          | *1 PC BRAKE BOOSTER                | 0.00  | 0.00  | *400.00 F   |
| 11  | 1   |          | *1 PC BRAKE MUSTER PUMP            | 0.00  | 0.00  | *220.00 F   |
| 12  | 1   |          | *1 PC RH HEADLAMP                  | 0.00  | 0.00  | *310.00 F   |

F=Franchise part.

Sub Total (S\$) 2,920.00

+ Margin on L,N Items 10.00% (S\$) 292.00

Total Parts (S\$) 3,212.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## Estimates on Labour


No Particulars

### Labour Items

| Labour Items                                                                                                                         | Lab.Type | Amount     |
|--------------------------------------------------------------------------------------------------------------------------------------|----------|------------|
| 1 REMOVE & REFIX FRT WINDSCREEN GLASS                                                                                                | New      | 60.00      |
| 2 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING                                                                               | New      | 250 280.00 |
| 3 REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS                                                                                 | New      | 100.00     |
| 4 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMPS,FRT WIPER ASSY,CUT,WELD & RENEW FRT PANEL,FRT WIPER PANEL,KNOCKOUT AND REALIGN THE SAME | New      | 600 750.00 |
| REMOVE & REFIX TOP ROOF LINING, CARPET, ETC                                                                                          | New      | 80.00      |
| REMOVE & REFIX BRAKE BOOSTER AND MUSTER PUMP AND CHECK SYSTEM                                                                        | New      | 80 150.00  |
| PUTTY & RESPRAY ON FRT PANEL,FRT GRILLE,FRT WIPER PANEL,FRT BUMPER                                                                   | New      | 600 700.00 |
| Gross Labour Cost (S\$)                                                                                                              |          | 2,120.00   |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)  
**ASIA TUNNEL PTE LTD**

Singapore

**PARTICULARS OF CLAIM**

|                               |                                                |                    |                                                                         |
|-------------------------------|------------------------------------------------|--------------------|-------------------------------------------------------------------------|
| Claim Type:                   | THIRD PARTY                                    | Ref. No:           | TP/CHINA(YN8665J)                                                       |
| Policy No:                    | DMCVSNW00010172202                             | Date of Loss:      | 07/02/2023                                                              |
| Vehicle Reg. No.:             | GBE9009S                                       | Driveable?         |                                                                         |
| Party At Fault:               | UNKNOWN                                        |                    |                                                                         |
| Driver (TP):                  | SEKAR MUTHAIAH                                 | Driver (Insured):  | JOSEPH VINCENT DAVID                                                    |
| Make/Model:                   | TOYOTA DYNA 1.5T, 3.0 (M)                      | Vehicle Reg. Date: | 18/04/2016                                                              |
| Vehicle Colour:               | SILVER                                         | Chassis No:        | JTFAT35Y90K206179                                                       |
| Engine No:                    | 1KD2592516                                     |                    |                                                                         |
| Odometer:                     | 0 KM                                           |                    | <i>Not with on the<br/>11 Sep @<br/>Puchong After Repair<br/>6 days</i> |
| Paint Type:                   |                                                |                    |                                                                         |
| Total Loss?                   | NO                                             |                    |                                                                         |
| Est. Duration of Repair (day) | 0                                              |                    |                                                                         |
| Description of Accident/Loss  | REFER TO GIA REPORT ATTACHED.                  |                    |                                                                         |
| Remarks:                      | VEHICLE CURRENTLY LYING AT WOODLANDS WORKSHOP. |                    |                                                                         |
| Present Location:             | CHENG HOE MOTOR PTE LTD (WOODLANDS)            |                    |                                                                         |

| <b>COST OF CLAIMS</b>     | <b>Amount</b>   |
|---------------------------|-----------------|
| Parts                     | 3,212.00        |
| Miscellaneous Items       | 0.00            |
| Labour                    | 2,120.00        |
| Paintwork Labour          | 0.00            |
| Towing                    | 0.00            |
| <b>Gross Total (\$\$)</b> | <b>5,332.00</b> |
| <b>+ GST 8.00% (\$\$)</b> | <b>426.56</b>   |
| <b>Nett Amount (\$\$)</b> | <b>5,758.56</b> |

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 08/02/2023 18:07 (SGT)  
Reported by ..... Driver  
Date of Accident ..... 07/02/2023 14:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... 121 UPP ALJUNIED RD(CONSTRUCTION SITE)  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBE9009S

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... FU CHENG BUILDING CONSTRUCTION PTE LTD  
Company Reg No ..... 2XXXXX354W  
Email Address ..... office@fucheng-hs.com  
Mobile Phone No ..... (Phone) +65-91476158  
Alternative Phone No ..... -

### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... TOYOTA DYNA 150 MANUAL  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Employment  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Manual  
CC ..... 2982

### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance (Singapore) Pte. Ltd.  
Policy Number / Cover Note Number ..... DMCVSNW00038072203

### DRIVER

Name of Driver ..... SEKAR MUTHAIAH  
Passport No/FIN ..... GXXXX874K  
Date Of Birth ..... 16/02/1997  
Occupation ..... Outdoor

Circumstance of the Accident

NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

☐ Claim Own Policy


☒ Claim Third party

☐ Claim OD/ TP at other workshop ( )

☐ Reporting Only

Sketch Plan

CONSTRUCTION SITE




I parked in the Construction Site at around 2:30pm on 7th Feb 2023. My lorry was stationary at the time, at 2:00pm another lorry YN8665J - try to park in front of me, the distance between my lorry front <sup>portion</sup> was about 1 metre, when the YN8665J and YN8665J back released the hand break, the lorry rolled back and hit my lorry front portion

#### Declaration

I/We declare the foregoing particulars are true in every respect.



 08.02.2023

Driver's Signature (if driver is not the policyholder) / Date & Time

 8/2/23  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card) (WL)