



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN: HO WINNIE

Ref: CS/HSB23001639/Anp3e2

Date: 11/05/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6986Z	Veh. Inspected	SNH 5701U
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04JD3	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	14/02/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	KMHLN41ETNU340928	Colour	WHITE
Odometer	17089 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	KUMHO	6 mm
L/H Front Tyre	225/45 R17	KUMHO	6 mm
R/H Rear Tyre	225/45 R17	KUMHO	6 mm
L/H Rear Tyre	225/45 R17	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2023	Inspection Date	15/02/2023
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**