

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202332005316 Date: 17th March 2023

Our Ref: CS6/AIS23001643/Uqy3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SNH 5016P ACCIDENT ON 10/02/2023

We thank you for your instruction on 14/02/2023.

The following vehicle information was recorded:

Registration Number : SNH 5016P

Make & Model : Mazda Mazda3 5-Door Hatchback 1.5L SP.6EAT

Chassis Number : JM6BM44A8G0323417

Year of Registration : 2015 Engine Capacity : 1496 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.