

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
MAK
KA WING
SINGAPORE

Document no.
Document date 14-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003925/ 1
Job order date 10-02-2023
Service Advisor Dass Anthonidas Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMW1782U	5E33MDA1	06-11-2020	TMBBC7NE2L0045801	Octavia Amb 1.4 I TSI 110kW MY20	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5E5807421G	Cover For REAR BUMPER	1	pcs.	1,656.46	#6	1,656.46	1,788.98
5Q0919275C GRU	Sensor Primed	4	pcs.	194.63	#6	778.52	840.80
5Q0919133 9B9	Seal Ring Satin Black	4	pcs.	1.53	#6	6.12	6.61
5E5919485A	Sensor Bracket	1	pcs.	12.39	#6	12.39	13.38
5E5919485	Sensor Bracket	2	pcs.	12.39	#6	24.78	26.76
5E5919486A	Sensor Bracket	1	pcs.	12.39	#6	12.39	13.38
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37	80.32
5E5807393B	Guide Piec	1	pcs.	60.35	#6	60.35	65.18
	LHR BUMPER BRACKET (SIDE)						
5E5807394B	Guide Piec	1	pcs.	60.35	#6	60.35	65.18
	RHR BUMPER BRACKET (SIDE)						
5E5807305C	Reinforcem	1	pcs.	613.66	#6	613.66	662.75
5E5807521	Spoiler	1	pcs.	162.65	#6	162.65	175.66
	LABOUR	21	pcs.	720.00	#6	2,332.80	2,332.80
	SPRAY PAINTING	21	pcs.	680.00	#6	2,040.00	2,203.20
	ALLIANZ DIRECT						
	DOA:09/02/2023						
	TP VEH NO:SLJ9303Y						
	SURVEY BY:						

Quotation valid till 17-02-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	7,746.68	8%	680.53	8,506.68	9,187.21
Total	760.00	7,746.68		680.53	8,506.68	9,187.21

Customer

Service Advisor

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
MAK
KA WING
SINGAPORE

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

14-02-2023
5211052769
201903913C
30001
2023003925/ 1
10-02-2023
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMW1782U	5E33MDA1	06-11-2020	TMBBC7NE2L0045801	Octavia Amb 1.4 I TSI 110kW MY20	20

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 9001068
3 days
P/P
27/02/23 @ 1300
Resurvey before paint

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Tax invoice Preview

Page

1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
MAK
KA WING
SINGAPORE

Document no.
Document date 10-03-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023005802/ 1
Job order date 01-03-2023
Service Advisor Dass Anthonidas
Christopher

License plate SMW1782U	Model code 5E33MDA1	First registration 06-11-2020	VIN TMBBC7NE2L0045801	Model Octavia Amb 1.4 I TSI 110kW MY20	Mileage 46,592
---------------------------	------------------------	----------------------------------	--------------------------	---	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5E5807421G	Cover For REAR BUMPER	1	pcs.	1,656.46	10.00% #6	1,490.81	1,610.07
5Q0919133 9B9	Seal Ring Satin Black	4	pcs.	1.53	10.00% #6	5.51	5.95
5E5919485A	Sensor Bracket	1	pcs.	12.39	10.00% #6	11.15	12.04
5E5919485	Sensor Bracket	2	pcs.	12.39	10.00% #6	22.30	24.08
5E5919486A	Sensor Bracket	1	pcs.	12.39	10.00% #6	11.15	12.04
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	10.00% #6	76.18	82.27
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	10.00% #6	66.93	72.28
5E5807521	Spoiler	1	pcs.	162.65	10.00% #6	146.39	158.10
4F0973703	Flat Contact Housing With (SCK) AO 8/3/2023	2	pcs.	10.93	10.00% #6	19.67	21.24
000979940	Butt Connector Watertight	6	pcs.	8.92	10.00% #6	48.17	52.02
	LABOUR	1	pcs.	720.00	#6	720.00	777.60
	SPRAY PAINTING	1	pcs.	680.00	#6	680.00	734.40
	ALLIANZ DIRECT DOA:09/02/2023 TP VEH NO:SLJ9303Y SURVEY BY: MR RASUL						

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	760.00	3,298.26	210.92	8%	324.66	210.92	4,058.26	4,382.92
Total	760.00	3,298.26	210.92		324.66	210.92	4,058.26	4,382.92

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

Payment in respect of any purchased services, packages inclusive of Prepaid Service Repair Package, or promotional items are strictly non-refundable.