

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: **HL Assurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1707
Policy No:	MP309471	Date of Loss:	11/02/2023
Vehicle Reg. No.:	SLM5514R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM JUNWEN, LESLIE	Contact No:	+6581137178
Make/Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Vehicle Reg. Date:	31/03/2017
Vehicle Colour:	BROWN	Chassis No:	SJNFEAJ11U1788100
Engine No:	HRA2337835A		
Odometer:	72792 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	6,683.25
Miscellaneous Items	145.00
Labour	2,160.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,988.25
+ GST 8.00% (S\$)	719.06
Nett Amount (S\$)	9,707.31

This claim is handled by: **CHAN PEI PEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>bt</i>	0.00	0.00	*700.00 F
2	1		*Bonnet hinge RH/LH@2*\$50 <i>Xnn</i>	0.00	0.00	X *100.00 F
3	1		*Headlamp RH/LH@2*\$450 <i>cn</i>	0.00	0.00	*900.00 F
4	1		*Front bumper <i>cut</i>	0.00	0.00	*450.00 F
5	1		*Front bumper side retainer RH/LH@2*\$35 <i>Xnn</i>	0.00	0.00	X *70.00 F
6	1		*Front bumper towing cover <i>cut</i>	0.00	0.00	*25.00 F
7	1		*Center grille <i>cn</i>	0.00	0.00	*350.00 F
8	1		*Center grille logo badge <i>cn</i>	0.00	0.00	*60.00 F
9	1		*Front bumper sponge <i>cn</i>	0.00	0.00	*150.00 F
10	1		*Front reinforcement <i>Xnn</i>	0.00	0.00	X *450.00 F
11	1		*Front lower reinforcement <i>Xnn</i>	0.00	0.00	X *250.00 F
12	1		*Front bumper lower sponge RH/LH@2*\$50 <i>Xnn</i>	0.00	0.00	X *100.00 F
13	1		*Front chassis member bracket RH/LH@2*\$100 <i>Xnn</i>	0.00	0.00	X *200.00 F
14	1		*Horn - high pitch <i>cn</i>	0.00	0.00	*90.00 F
15	1		*Condenser <i>bt</i>	0.00	0.00	*650.00 F
16	1		*Radiator <i>X</i>	0.00	0.00	X *650.00 F
17	1		*Fan cowling set <i>X</i>	0.00	0.00	X *550.00 F
18	1		*Radiator air guide RH/LH@2*\$85 <i>LH-cn / RH-? X</i>	0.00	0.00	85 *170.00 F
19	1		*Front fender LH <i>repair</i>	0.00	0.00	X *450.00 F
20	1		*Front fender RH (Repair refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (S\$)	3460	6,365.00
+ Margin on L,N Items 5.00% (S\$)	56+	318.25
Total Parts (S\$)	3633	6,683.25

Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Center grille clips <i>ne</i>	25.00
2	1	Coolant <i>ne</i>	50.00
3	1	Front bumper clips <i>ne</i>	35.00
4	1	Front car plate with holder <i>ne</i>	35.00
Sub Total (S\$)			145.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	600 1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800 1,000.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30 60.00
4	To remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	New	80 100.00
Gross Labour Cost (S\$)			2,160.00

Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3633

115

1510

630

5888

206

4710

Ram

Hp 9001w68

6 days

4s

16/02/23 @ 1435

EXCESS: 300

Revert

Resy after repair

4s - \$4,700/6 days

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SLM5514R/02/03/2023 18:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front wheel arch garnish RH/LH@2*\$300 <i>cm</i>	0.00	0.00	*600.00 F
			Sub Total (\$\$)			600.00
			+ Margin on L,N Items 5.00% (\$\$)			30.00
			Total Parts (\$\$)			630.00 ✓

Wah Hong Motors & Credit Pte Ltd/SLM5514R/02/03/2023 18:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS