

DMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH6232R

DATE 10.02.2023

MAKE REG. 25.08.2022

CHIANG/INCOME

MODEL BYD

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>Scr # R dent ✓</i>			\$3,301.87
1	REAR BUMPER LOWER COVER <i>dent ✓</i>		750.75	\$2,013.75
1	REAR BUMPER REINFORCEMENT <i>? x</i>			\$528.75
1	REAR BUMPER REFLECTOR RH <i>? x</i>		\$48.00	\$48.00
1	REAR BUMPER REVERSE LAMP <i>? x</i>			\$375.00
2	REAR BUMPER RETAINER LH/RH <i>? x</i>		\$87.00	\$174.00
	SUB TOTAL		750.75	\$6,441.37
	LESS 20%		150.15	\$1,288.27
			600.60	\$5,153.09
				\$240.00
1	REVERSE SENSOR <i>? XNN</i>			\$50.00
1	REAR BUMPER MAT <i>mc</i>			\$40.00
1	BUMPER LINE STICKER <i>wcc</i>			\$330.00
	Labour Charge			\$700.00 <i>400</i>
	Panel Beating			\$400.00 <i>250 400</i>
	Spray Painting Charge			\$60.00 <i>XNN</i>
	Tuff Coat			\$60.00 <i>30</i>
	Check Wiring			\$1,220.00
	TOTAL LABOUR			\$1,220.00
	ESTIMATE TOTAL			\$6,703.09
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

FT
= 1370.60

1520.60

2 days P/P

11 Feb 13/2/23

410pm

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.03.2023

Time: 08:09:58

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305545338
REGN NO : SH 6232R
MILEAGE : 0000000000
MAKE : BYD
MODEL : NEW E6
DATE OF REGN : 25.08.2022
DATE/TIME IN : 10.02.2023 14:50
ACCIDENT DATE : 10.02.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0401-0034-G REAR BUMPER LOWER BODY 1 750.75 20.00 600.60


SUB-TOTAL : 600.60

JOB NATURE

0000 PB PANEL BEATING SH6232R TP 400.00
0001 SP SPRAYPAINT CHARGE 400.00
0002 17-01 CHECK ALL LIGHTING 30.00
0003 20-05 REAR BUMPER MAT 50.00
0004 20-05 REAR BUMPER LINE STICKER 40.00

SUB-TOTAL : 920.00

TOTAL : 1,520.60


MVA NAME & SIGNATURE
DATE:

SURVEYOR NAME & SIGNATURE
DATE: AUTHORIZED : YES / NO