



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2301391

10 MARINA BOULEVARD

INV Date 09/03/2023

#48-01 MARINA BAY FINANCIAL CENTRE

Reference CS3/HSB23001700/Uvp3e2

TOWER 2

Code HSB

SINGAPORE 018983

ATTN: LOW GARNET

PROFESSIONAL SERVICE FEE

Vehicle No. SMM 1550A

Insured Veh. SHA 9877C

Claim No. S3M04J5R

Policy No. VFX/P2419140

Accident Date 08/02/2023

Inspection Date 15/02/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 15.02.2023)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 03.03.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM