




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS3/HSB23001700/Uvp3e2 Date: 09/03/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 9877C	Veh. Inspected	SMM 1550A
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S3M04J5R	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	14/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72001389	Colour	BLUE
	Odometer	269910 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	KAPSEN	6 mm
	L/H Front Tyre	185/60 R15	KAPSEN	6 mm
	R/H Rear Tyre	185/60 R15	KUMHO	6 mm
	L/H Rear Tyre	185/60 R15	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
5. General Information				
	Accident Date	08/02/2023	Inspect Date / Time	15/02/2023 (10:55 AM)
	Survey held at	NEW ZEN WERKZ PTE LTD 3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	

Report Ref No. CS3/HSB23001700/Uvp3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.