LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sharon Lim Date: 17 Feb 2023 Attn:

Preliminary Advice

Vehicle No : SNA8769S Accident Date : 12/02/2023

Make : KIA SORENTO Policy No. : SP2001882155-01

: 15/02/2023 Excess Assignment Date : S\$1,100.00

Est. Duration of Repair Date of Inspection : 16/2/2023 : 14

Inspection At : CYCLE & CARRIAGE KIA PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	138,558.00
Revised Amount	:S\$	4,458.00
Check Items (Estimated)	:S\$	133,700.00
Total	:S\$	138,158.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 176,000.00 COE / PARF Rebate :S\$ 70,405.00

Salvage Value :S\$

Margin for Repair :S\$ 105,595.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Pending investigation

Part by part repair as repairer is agent workshop.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.