## MEORT TRANSPORTATION PTE L'TD

REPAIR ESTIMATE

Vehicle No. : SHC1766G : Toyota Make

Model

: Prius (G4A)

Date: 11/02/2023

Insurance: INCOME

MVA: MS. LOKE YY

| Qty | Parts Description / Labour   | Туре           | Unit Price                   | Amount   |               |
|-----|--|----------------|------------------------------|--|---------------|
|     | REAR BUMPER SCI TE BI  | 59 5 5         |                              | \$ 503.04  |               |
| 4   | REAR BUMPER CLIPS X NN   |                |                              | \$ 22.00   |               |
| 1   | 1 REAR BUMPER LOWER COVER SC   |                |                              | \$ 654.96  |               |
| ,   | A DEAD DUMPER COVER COVER 3  | B. Carrie      |                              | \$ 378.32  |               |
|     | 1 REAR BUMPER REINFORCEMENT ? X 1 BACK DOOR GARNISH ASSY ? B             | great y not    |                              | \$ 1,054.71  |               |
|     | 1 BACK DOOR GARNISH ASSY ( D)  | Sunt of        |                              | \$ 62.14   |               |
|     | 1 REAR TRUNK LID LOGO (PRIUS) Nec  | and the same   |                              | \$ 62.14   |               |
|     | 1 REAR TRUNK LID LOGO (HYBRID) INCL                                      |                |                              |  | rio d         |
|     | BOOTLID SCT R  |                |                              |  |               |
|     |  | 100 may 2 mg   |                              |  |               |
|     | SUB TOTAL  | er mark        |                              | \$ 2,737.31  | 2334          |
|     | LESS 25%   |                |                              | \$ 684.33  | 584           |
|     | DISCOUNTED TOTAL   |                |                              | \$ 2,052.98  | 1752          |
|     | DISCOUNTED TOTAL   |                |                              |  |               |
|     | REAR TRUNK LID COMFORT & TEL NO. STICKER MC                              |                |                              | \$ 60.00   | Nett          |
|     | REAR TRUNK LID COMPORT & TEL NO. STICKER REAR TRUNK LID APPS STICKER NEC |                |                              | \$ 40.00   | Nett          |
|     | REAR BUMPER RUBBER MAT NCC   |                |                              | \$ 50.00   | Nett          |
|     | REAR REVERSE SENSOR ?  |                |                              | \$ 135.70  | Nett          |
|     | REAR REVERSE SENSOR  |                |                              | \$ 285.70  | Nett          |
|     |  |                |                              |  |               |
|     | Labour Charge  |                | e a contratto                | 400.00   | 350           |
|     | PANEL BEATING  |                |                              | \$ 400.00<br>\$ 600.00   | 500           |
|     | SPRAY PAINTING CHARGE  | Ministrate A   | HARLING A. G.                | Control of the Contro | OCT I COMPANY |
|     | REMOVE/REFIX REVERSE SENSOR  |                |                              |  | <b>亥?3</b> 4  |
|     | TOTAL LABOUR   | P. (2.3)       |                              | \$ 1,060.00  |               |
|     | ESTIMATE TOTAL   | and refer to   |                              | \$ 3,398.68  | 278           |
|     | ESTIMATE TOTAL   | A LEAST BEAUTY | STATE OF THE PROPERTY OF THE |  | = 556.        |
|     |  |                |                              | 201  | 529.          |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

FT = 2226.20 \$\times 2200 \text{y}

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: