

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2379J
 MAKE HYUNDAI
 MODEL I40

DATE: 13.12.22
 MVA JUMANI
 DOA: 10.12.22

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>Paint</i>			\$553.00
1	REAR BUMPER UNDER COVER ? X nn			\$228.00
1	REAR BUMPER BEAM ? X nn			\$428.40
10	REAR BUMPER CLIPS <i>ml</i>			\$22.00
1	REAR BUMPER SPONGE ? X nn			\$119.50
1	REAR BUMPER MOULDING <i>Scr</i>			\$85.00
1	BOOTLID <i>Scr / Dent</i>			\$2,609.80
1	BOOTLID LOWER GARNISH <i>ml</i>			\$227.90
1	BOOTLID EMBLEM - I40 <i>NEL</i>			\$67.90
1	BOOTLID EMBLEM - CRDI <i>ml</i>			\$52.40
1	BOOTLID EMBLEM - H <i>ml</i>			\$63.10
SUB TOTAL				\$4,457.00
LESS 20%				\$891.40
DISCOUNTED TOTAL				\$3,565.60
BOOTLID APPS LOGO <i>ml</i>				\$40.00 NET
REVERSE SENSOR ? X nn				\$135.70 NET
BOOTLID COMFORT LOGO <i>ml</i>				\$30.00 NET
BOOTLID COMFORT TEL.NO LOGO <i>ml</i>				\$30.00 NET
SUB-TOTAL				\$235.70
LESS 10%				\$23.77
\$213.93				212.13
Labour Charge				
PANEL BEATING				\$600.00 <i>560</i>
SPRAY PAINT				\$600.00 <i>500</i>
REMOVE / REFIX REVERSE SENSOR				X? \$50.00 <i>\$</i>
TOTAL LABOUR				\$1,250.00
ESTIMATE TOTAL				\$5,029.53
5027.73				<i>4104.88</i>
20% =				<i>820.97</i>
=				<i>3283.90</i>
T2				<i>3300</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 days L/S 1rdm
13/12/23 5pm