



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LIP22011033/Eqy3-1

LIBERTY INSURANCE PTE LTD

51 CLUB STREET, #03-00
LIBERTY HOUSESINGAPORE 069428

Ref: ~~CS3/LIP22011033/43~~

Date: ~~04/11/2022~~ 16/02/2023

Code: LIP

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 7571S	Veh. Inspected	XE 2625Z
Policy No.		Coverage (\$)	0.00
Claim No.	BVS22/1209	Excess (\$)	0.00
Assign From	TED SEAH	Assign Date	04/11/2022 16/02/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/10/2022	Inspection Date	
Survey held at	LENG YONG MOTOR WORKSHOP 27-A JURONG PORT ROAD #01-28 JTC IND SERVICE CENTRE SINGAPORE 619101		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--