7/20/23, 10:49 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III23001742/AYA3Q2

**Date:** 20/07/2023

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0000947

Claimant Vehicle SKZ2516Z Insured Vehicle No: SMQ3573A

Date of Loss: 15/02/2023 Nature of Claim: TP Claim No: MFL2023D0002307

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKZ2516Z

 Make & Model:
 HONDA VEZEL, 1.5 X (A)
 Engine No:
 L15B4025790

 Reg. Date:
 15/01/2016 (Man. Year: 2015)
 Chassis No:
 RU11105787

 Colour:
 Blue
 Odometer:
 107976 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	0.00	6,900.00	-6,900.00	
+ GST 8.00/8.00% (S\$)	0.00	552.00	-552.00	
Nett Amount (S\$)	0.00	7,452.00	-7,452.00	
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		8,378.75		

**INSPECTION** 

Date of Assignment: 16/02/2023

Cas Garage Pte Ltd (HQ)

Date Inspected: 17/02/2023 Inspected At: No.1, Kaki Bukit Ave 6, #02-22 Autobay

Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

### **REPAIR DETAILS**

Reference

7/20/23, 10:49 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Feb 2023)

Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ2516Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

7/20/23, 10:49 AM Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >