



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS/III23001745/Kny3

Date: 16/02/2023

Code: III2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBE 8411U
Policy No.	D19MCV0001408	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KRISHNAN BHUVANESWARI	Assign Date	16/02/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/02/2023	Inspection Date	16/02/2023
Survey held at	14 Ang Mo Kio Street 63, Blk B, 569116 Ang Mo Kio		
Repairer	KGC WORKSHOP PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.