

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 13 May 2023)
Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	87150-25060	*Radiator Heater Unit <i>Aircan</i>	0.00	0.00	*580.00 F ✓
Sub Total (\$\$)						580.00
+ Margin on L,N Items 10.00% (\$\$)						58.00
Total Parts (\$\$)						638.00 ✗

Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	top up aircon gas	New	50.00 80.00
Gross Labour Cost (\$\$)			80.00

Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >