



*Not Notified  
L1 Rep &  
Survey After Paint  
Selayi*

### KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240  
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482  
Email:kentsengcarservices@gmail.com

M/s MS First Capital Insurance Limited	DATE	15.02.2023
36 Robinson Road #16-01 City House	CAR NO	SLD 2147 J
S 068877 Tel 65073848 Fax 65073849	MAKE	Mercedes

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.  
YOUR INSURED : XE 4936 M

Pc	Pcs	WDD2120362B312977	UNIT PRICE	AMOUNT	
1	pc	Rear bumper		\$1,641.00	✓
10	pcs	Rear bumper clips	\$6.00	\$60.00	✓
2	pcs	Rear bumper side retainer	\$41.00	\$82.00	X
2	pcs	Rear bumper side bracket	\$77.00	\$154.00	?
1	pc	Rear bumper lower lip protector		\$546.00	✓
1	pc	Rear bumper lower chrome moulding		\$359.00	?
4	pcs	Rear bumper left side reverse sensor	\$264.00	\$1,056.00	?
1	pc	Rear bumper reinforcement		\$814.00	?
1	pc	Rear bumper tow cover		\$68.00	X
2	pcs	Rear exhaust chrome cover (LH & RH)	\$352.00	\$704.00	X
1	pc	Rear boot lid number plate garnish		\$279.00	X
2	pcs	Rear boot lid reflector (LH & RH)	\$440.00	\$880.00	X
1	pc	Rear boot lid "E250" emblem		\$79.00	✓
1	pc	Rear boot lid "TG-TRONIC" emblem		\$85.00	✓
1	pc	Rear boot lid "Mercedes" logo		\$125.00	✓
1	pc	Rear boot lid top lock		\$376.00	✓
1	pc	Rear end panel		\$1,539.00	?
1	pc	Rear end panel top garnish		\$136.00	?
8	pcs	Rear end panel top garnish clips	\$6.00	\$48.00	?
2	pcs	Tail lamp (LH & RH)	\$704.00	\$1,408.00	X
		Apply anti rust and sealant for accident repaired area.		\$150.00	?
		Straightening, repairing and realigning onto the rear affected area, cutting rear end panel, knocking rear spare tyre tank panel, dismantle and replace the above affected parts.		\$2,000.00	?
		Spray painting for all accident affected parts, rear bumper, rear reinforcement bar, rear end panel, rear boot lid & rear spare tyre tank panel.		\$1,500.00	7501
		Reprogrammed the error codes after the accident repair works.		\$250.00	?
		To testing, checking, dismantle & replace rear bumper reverse sensor.		\$80.00	601

Susan Lim

KENT SENG CAR SERVICES.

LKK Auto Consultants hence notify the Repairer of the following:	\$80.00
Page of 1 Total	\$14,419.00

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: