

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: MAZDA 3

Engine/Chassis No.:

Date of accident: 04.02.23


Damaged area: N/S Front

Date: 24/02/2023

Claim Type: TP

VRN: SND51725

NOT Ashwin
 : \$500
 Repair After Pains
 2 days



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	FRONT BUMPER	1	\$ 1,311.00	\$ 1,311.00
2	FRONT REINFORCEMENT	1	\$ 679.00	\$ 679.00
3	FRONT BUMPER RETAINER	2	\$ 115.00	\$ 230.00
4	FRONT REINFORCEMENT SPONGE	1	\$ 280.00	\$ 280.00
5	FRONT GRILLE	1	\$ 671.00	\$ 671.00
6	FRONT GRILLE SIDE CHROME MOULDING N/S	1	\$ 277.00	\$ 277.00
7	FRONT BUMPER LICENCE PLATE BASE	1	\$ 127.00	\$ 127.00
8	FRONT GRILLE LOGO INNER BRACKET	1	\$ 89.00	\$ 89.00
9	FRONT GRILLE INNER BRACKET	1	\$ 349.00	\$ 349.00
10	FRONT CENTER BRACE	1	\$ 69.00	\$ 69.00
11	FRONT BUMPER FOGLAMP COVER N/S	1	\$ 360.00	\$ 360.00
12	HEADLAMP N/S	1	\$ 3,465.00	\$ 3,465.00
13	FRONT BUMPER UNDER COWLING	1	\$ 164.00	\$ 164.00
14	FRONT GRILLE LOGO	1	\$ 65.00	\$ 65.00
Subtotal				\$ 8,136.00
List discount				20.00%
Total				\$ 6,508.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	FRONT BUMPER CLIPS	10	\$ 5.50	\$ 55.00
2	FRONT GRILLE CLIPS	6	\$ 5.50	\$ 33.00
3	FRONT BUMPER UNDER COWLING CLIPS	6	\$ 5.50	\$ 33.00
4	FRONT LICENCE PLATE & GARNISH	1	\$ 55.00	\$ 55.00
5	SUNDRIES	1	\$ 50.00	\$ 50.00
Total				\$ 226.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00

Repair Estimate

2	To disconnect wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ <i>nn</i> 50.00	X
3	To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality.	0.5	\$ <i>nn</i> 100.00	X
4	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00	400/
5	To rust proof all affected portions after repair.	0.5	\$ <i>nn</i> 100.00	X
Total labour			\$ 2,050.00	
Estimate Grand Total			\$ 8,784.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: