



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: SALLY NG			Ref: CS3/INC22004387/Dny3e2-1 Date: 13/07/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMT 9215D	Veh. Inspected	SLD 2821X
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1171706-002	Excess (\$)	0.00
	Assign From		Assign Date	16/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS E	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053HY9305168732	Colour	GREEN
	Odometer	269954 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	FIRENZA	6 mm
	L/H Front Tyre	195/55 R15	FIRENZA	6 mm
	R/H Rear Tyre	195/55 R15	FIRENZA	6 mm
	L/H Rear Tyre	195/55 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/05/2022	Inspection Date	18/05/2022
	Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days