



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/INC22004387/ny3-1	
<b>NTUC INCOME INSURANCE CO-OPERATIVE LTD</b> 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Ref: <del>CS3/INC22004387/y3</del> Date: <del>10/05/2022</del> 16/02/2023  Code: INC		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>					
Insured Veh.	SMT 9215D		Veh. Inspected	SLD 2821X	
Policy No.			Coverage (\$)	0.00	
Claim No.	MT/1171706-002		Excess (\$)	0.00	
Assign From	JESS TOH		Assign Date	<del>10/05/2022</del> 16/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>					
Make & Model			c.c	0	
Engine No.	HIDDEN		Year of Reg.		
Chassis No.			Colour		
Odometer	-		Steering		
Brakes			Modification		
General					
<b>3. Conditions of Tyres</b>					
		Size	Make	Balance	
R/H Front Tyre				mm	
L/H Front Tyre				mm	
R/H Rear Tyre				mm	
L/H Rear Tyre				mm	
<b>4. Description of Damages</b>					
<b>5. General Information</b>					
Accident Date	08/05/2022		Inspection Date	11/05/2022	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
<b>5a. Remarks</b>					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					