

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 27 Feb 2023

Preliminary Advice

Vehicle No	: SMG2703B	Accident Date	: 14/02/2023
Make	: HONDA HR-V	Policy No.	: SP2003942370-01
Assignment Date	: 16/02/2023	Excess	: S\$500.00
Date of Inspection	: 17/02/2023	Est. Duration of Repair	: 7 days
Inspection At	: SUCCESS UNITED PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,250.30 (Est \$12,122.70 + Supp \$127.60)
Revised Amount	:S\$	7,316.30 (Included Supp \$127.60)
Check Items (Estimated)	:S\$	2359.50
Total	:S\$	9,675.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	29,076.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,924.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on Supplementary Items.