

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0181/2023/EQ
DATE : 16-Feb-23
WIP : 63485

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS PRIYA VERMA
ADDRESS : BLK 134 TANJONG RHU ROAD
#02-04
SINGAPORE 436920
TELEPHONE : HP +65 92314204
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210012863-01
VEHICLE NO : **SMX 8198 E**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29/1/2021
ENGINE NO : CZD C23285
CHASSIS NO : WAUZZZF36M1058954
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Feb-23
PLACE OF ACCIDENT : KALLANG WAVE MALL CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 8198 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID.	S/N \$	280.00	X.
2	TO RENEW LHS 1/4 GLASS TO FACILITATE LHS REAR FENDER RENEWAL.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM TO AFFECTED GLASS.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR LHS 1/4 GLASS.	S/N \$	200.00 150	
5	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 280	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,600.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,180.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 8198 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,600.00 ✓	
8	TO DISMANTLE REAR BUMPER AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER AND REAR OUTER CROSS PANEL. RENEW LHS REAR DOOR, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 ✓	3500.
9	TO RESPRAY LHS REAR DOOR, DOOR HANDLE, LHS REAR FENDER, REAR CROSS PANEL, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES. TO CARRY OUT JOINT SEALER WORKS.	\$ 6,300.00 ✓	2575. 4.5 x 550 = 2475 Handle : 100 2575
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 18,472.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 8198 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Dented</i>	1	\$ 3,313.00	✓
2	REAR DOOR OUTER SEAL - LH <i>New</i>	1	\$ 159.00	✓
3	REAR DOOR CATCH <i>?</i>	1	\$ 141.00	?
4	REAR DOOR ATTACHMENT PARTS <i>New</i>	1	\$ 338.00	+
5	REAR EXTERIOR DOOR HANDLE - LH <i>lit</i>	1	\$ 231.00	✓
6	REAR DOOR HOUSING - LH <i>Regis</i>	1	\$ 32.00	+
7	REAR DOOR MOUNTING BAR <i>New</i>	1	\$ 183.00	+
8	REAR DOOR COVER - LH <i>New</i>	1	\$ 286.00	+
9	REAR SIDE PANEL - LH <i>Dented</i>	1	\$ 3,853.00	✓
10	REAR CROSS PANEL <i>New</i>	1	\$ 348.00	+
11	REAR QUARTER WINDOW - LH <i>New</i>	1	\$ 724.00	✓
12	REAR WHEEL COVER - LH / RH <i>New</i>	2	\$ 598.00	✓
13	ACRYLIC SEALANT <i>2</i>	S/N	\$ 180.00	✓
14	CAVITY WAX	S/N	\$ 140.00	✓
15	STONE CHIP <i>New</i>	S/N	\$ 180.00	✓
16	METAL FILLER POWDER	S/N	\$ 280.00	✓
17	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
18	SUNDRIES <i>?</i>		\$ 600.00	?
TOTAL SPARE PARTS		:	\$ 11,686.00	
TOTAL LABOUR CHARGES		:	\$ 18,472.00	
GRAND TOTAL		:	\$ 30,158.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan Lj
SURVEYED DATE : 18/02/23
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 13 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT