



**KOMODO MOTORS PTE LTD**  
 127, Jalan Duta Suka, 11000, Singapore 11000  
 T: 65 6402 2888 Fax: 65 6402 2889  
 07980 1740538

**HYUNDAI**  
 (GST REGISTRATION NO: MR-8500364-4)

Date : 17/02/2023

**LONPAC INSURANCE BHD**

Attn: Motor Claims Department

Vehicle number : **SMN7728K**  
 Make and model : **AVANTE 1.6 4DR AUTO "S"**  
 Registration Date : 28/08/2019  
 Chassis number : **KMHD841CMKU934887**  
 Engine number : **G4FGKU171365**

Job No. :  
 Owner name : **MISLIMAYA BTE ISMAIL**  
 Date of Acc : 14/02/2023  
 Policy number : **A300658552AH**  
 Claim Type : **3rd Party Claim**

Items :	Estimate
1 BUMPER CLIP X10 <i>na</i>	865952T500 \$ 12.00
2 COVER ASSY-RR BUMPER UPR <i>ca</i>	86611F2AA1 \$ 500.10
3 COVER-RR BUMPER LWR <i>su</i>	86612F2AG0 \$ 353.50
4 MOULDING-L/PLATE REAR BUMPER <i>? de</i>	86619F2AA0 \$ 27.80
5 REFLECTOR/REFLEX ASSY-RR RH <i>xm</i>	92406F2500 \$ 221.60
6 REFLECTOR/REFLEX ASSY-RR LH <i>xm</i>	92405F2500 \$ 221.60
7 BEAM-RR BUMPER <i>xm</i>	86631F2AB0 \$ 294.80
8 LAMP ASSY-LICENSE PLATE, LH <i>xm</i>	92501F6000 \$ 32.30
9 LAMP ASSY-LICENSE PLATE, RH <i>xm</i>	92502F6000 \$ 32.30
10 STAY-RR BUMPER RH <i>xm</i>	86642F2AB0 \$ 78.60
11 STAY-RR BUMPER LH <i>xm</i>	86641F2AB0 \$ 78.60
12 BRACKET-RR BUMPER SIDE MTG, RH <i>? xm</i>	86614F2AA0 \$ 29.40
13 BRACKET-RR BUMPER SIDE MTG, LH <i>? xm</i>	86613F2AA0 \$ 29.40
14 PANEL ASSY-TRUNK LID <i>repair</i>	69200F2530 \$ 2,096.90
15 EMBLEM-AVANTE <i>na</i>	86310F2AA0 \$ 31.20
16 WEATHER STRIP-TRUNK LID <i>cut</i>	87321F2000 \$ 92.50
	\$ 4,132.60
Less 20% Discount	\$ 826.52
Material total	\$ 3,306.08

*Rasul*  
*Hp 90010068*  
*4 days*  
*P/P*  
*24/02/23 @ 1415*  
*Resy before part*

Body, Paint & Labour Items :	Estimate
1 To carry out accident body repair <i>@420 x 2</i>	\$ 2,100.00 <i>340 840</i>
2 Complete putty and spray paint all affected areas <i>@320 x 2</i>	\$ 1,718.00 <i>320 260 1020</i>
<b>Labour Charges:</b>	
3 To realign both Rear Tail lamp (S.NETT)	\$ 40.00 <i>xm</i>
4 To supply trunk sealant (S.NETT)	\$ 100.00 <i>xm</i>
5 To transfer trunk mechanism (S.NETT)	\$ 250.00 <i>xm</i>
6 To supply & install RR number plate (S.NETT)	\$ 40.00 <i>xm</i>
7 To carry-out body cavity preservation (S.NETT) (INCLUDING NEW PARTS AND CAOUTCHOU)	\$ 280.00 <i>? xm</i>
8 To check electrical system for proper functioning (S.NETT)	\$ 280.00 <i>180</i>
9 Sundries (S.NETT)	\$ 40.00 <i>20</i>
10 To supply & install 'S' Logo	\$ 35.00
Total	\$ 8,181.08
Excess	
Add GST 8%	\$ 654.49
<b>Grand Total</b>	<b>\$ 8,835.57</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

\*\*\* Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out\*\*\*

Vehicle number : **SMN7728K**  
Make and model : AVANTE 1.6 4DR AUTO "S"

Registration Date : 28/08/2019  
Chassis number : KMHD841CMKU934887  
Engine number : G4FGKU171365

**SUPPLEMENTARY**  
Job No. :  
Owner name : MISLIMAYA  
BTE ISMAIL  
Date of Acc : 14/02/2023  
Policy number : A300658552AH  
Claim Type : 3rd Party Claim

**Labour Charges:**

1 TO SUPPLY & REPLACE REVERSE SENSOR -95720F (S.NETT)

*Estimate*  
\$ 264.00 *aw ✓*

Total  
Add GST 8%

\$	264.00
\$	21.12
<b>\$</b>	<b>285.12</b>