

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page

1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
LEE
WEE LEONG
33 CHAI CHEE AVENUE
#19-244
SINGAPORE 461033

Document no.
Document date 20-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004868/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMR6433X	5E36UDR3	16-01-2020	TMBBU7NE3L0045044	Octavia RS 2.0 TSI 180kW w/o WC MY20	445.043

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
98018004	B&P CHECK SHORT CIRCUIT/HARNES REPAIR				#6	200.00	216.00
98018005	B&P DIAGNOSIS AND PROGRAMMING				#6	360.00	388.80
98018001	TO ALIGN LED HEADLIGHT				#6	100.00	108.00
98018003	B&P WHEEL ALIGNMENT				#6	300.00	324.00
98018001	R&R RIM & BALANCE				#6	100.00	108.00
5E0807221AA	Cover For FRT BUMPER	1	pcs.	1,750.00	28.00%	1,260.00	1,360.80
5E0807183A	Guide Pic BUMPER SIDE BRACKET LH	1	pcs.	47.28	28.00%	34.04	36.76
5E0919485H	Sensor Bra	1	pcs.	13.63	28.00%	9.81	10.59
5E0919486H	Sensor Bra	1	pcs.	13.63	28.00%	9.81	10.59
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	28.00%	60.94	65.82
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	28.00%	53.55	57.83
5E0807681H 989	Cover For LHS FOG LAMP GRILLE	1	pcs.	51.51	28.00%	37.09	40.06
5E0853793 041	Corner Tri LHS FOG LAMP GRILLE SIDE TRIM	1	pcs.	117.92	28.00%	84.90	91.69
5E2941015E	Unbekannt LHS H/LAMP	1	pcs.	2,189.09	28.00%	1,576.14	1,702.23
N 90959003	Bolthex.Hd.With Shoul.	2	pcs.	2.64	28.00%	3.80	4.10
5E0941699H	Led Fog La	1	pcs.	796.37	28.00%	573.39	619.26
5Q0955453R	Wash Water Reservoir WIPER TANK	1	pcs.	146.31	28.00%	105.34	113.77
444955647	Plug	1	pcs.	9.21	28.00%	6.63	7.16
443955465	Gasket	1	pcs.	2.36	28.00%	1.70	1.84
G 052184A2	Windshield Cleaner Concen	1	pcs.	22.22	28.00%	16.00	17.28
5E0821105C	Fender	1	pcs.	845.49	28.00%	608.75	657.45
N 90959602	Riveted Cap Nut	4	pcs.	2.84	28.00%	7.60	8.21
5E0821141A	Fender - B LHS FENDER BRACKET	1	pcs.	90.89	28.00%	65.30	70.52
5E0809957K	Wheelhouse LHS FENDER LINER	1	pcs.	214.23	28.00%	154.25	166.59
5E0807905B	FOIL LHR FENDER FOIL	1	pcs.	44.93	28.00%	32.35	34.94
5E0601025AHHA7	Alloy Whee LHS FRT RIM	1	pcs.	1,634.43	28.00%	1,176.79	1,270.93
311601361	Rubber Valve	1	pcs.	3.99	28.00%	2.87	3.10
5E0601025AHHA7	Alloy Whee LHS REAR RIM	1	pcs.	1,634.43	28.00%	1,176.79	1,270.93
311601361	Rubber Valve	1	pcs.	3.99	28.00%	2.87	3.10
	LABOUR	6	pcs.	560.00	2240	3,360.00	3,628.80
	SPRAY PAINT	8	pcs.	530.00	3710	4,240.00	4,579.20

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
LEE
WEE LEONG
33 CHAI CHEE AVENUE
#19-244
SINGAPORE 461033

Page 2/2
Document no.
Document date 20-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004868/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

License plate SMR6433X	Model code 5E36UDR3	First registration 16-01-2020	VIN TMBBU7NE3L0045044	Model Octavia RS 2.0 TSI 180kW w/o WC MY20	Mileage 445,043
---------------------------	------------------------	----------------------------------	--------------------------	---	--------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	ALLIANZ OD/RECOVERY DOA: 20/02/2023						

Quotation valid till 27-02-2023

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	1,060.00	14,660.71	2,745.85	8%	1,257.66	2,745.85	15,720.71	16,978.37

Customer

Service Advisor

VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).

All invoices are denominated in SGD, unless otherwise stated.

Tang Jm 17415749
'wp' 21/2/23 2:30pm
p/p Resurvey after repair
10 days
Tang Jm C/Insurance

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Supplementary or Omitted List



VEHICLE NUMBER: SMR6433X

MODEL OCTAVIA

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
	5E5945711	Taillight LHS TAILLIGHT OUTER	1	1004.71	wt ✓	1004.71 ✓ 423.39
	5E0823713	LHS FENDER TOP SPONGE	1	16.09	rel ✓	16.09 ✓ 11.58

\$ 1,020.80

Total Labour & Parts

SURVEY By

TAUFIK

\$1,020.80