4/3/23, 9:00 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23001854/SQY3Q2

03/04/2023 Date:

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MW008596 **Claimant Vehicle** 

SHA1197J Insured Vehicle No: SKV6154D No:

Date of Loss: 17/02/2023 Nature of Claim: TP Claim No: M2301125

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SHA1197J** 

TOYOTA PRIUS, 1.5 HYBRID (A) 2ZR2B84578 Make & Model: Engine No:

Reg. Date: 07/01/2019 (Man. Year: 2018) Chassis No: JTDKB3FU603077808

Colour: Odometer: 528493 km Blue

**Engine Capacity:** 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Good Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Good

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,261.16	2,633.64	627.52	19.24
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		2,220.00	1,560.00	660.00	29.73
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calcu	lated Gross Total (S\$)	5,492.16	4,204.64	1,287.52	23.44
Approved T	otal (Overridden) (S\$)		3,350.00		
	(S\$)	5,492.16	3,350.00	2,142.16	39.00
	+ GST 8.00/8.00% (S\$)	439.37	268.00	171.37	39.00
	Nett Amount (S\$)	5,931.53	3,618.00	2,313.53	39.00

**INSPECTION** 

Date of Assignment: 20/02/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 20/02/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 9:00 AM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)

Parts: 144 TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1197J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL SUB ASSY RH	Buckled	1,258.30 FL	*1,258.30 FL
2	1		*ROCKER PANEL GARNISH RH	Broken / Scratched	576.00 FL	*576.00 FL
3	1		*REAR FENDER RH	Repair	836.70 FL	*- FL
4	1		*REAR WHEEL RIM RH	Scratched	1,570.55 FL	*1,570.55 FL
5	1		*REAR DOOR COMFORT APPS STICKER RH	Necessary	80.00 F	*80.00 F
F=Fra	anchise	part. L=ListIte	emDisc.	-		
				Sub Total (S\$)	4,321.55	3,484.85
			- List Item Discount on	L Items 25.00/25.00% (S\$)	1,060.39	851.21
				Total Parts (S\$)	3,261.16	2,633.64
			Report was unsubmitted durin	g this print-out.		

# Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,100.00	700.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	120.00	40.00
4	TRANSFER OF DOOR	New	120.00	40.00
5	TUFF KOTE	New	80.00	30.00
		Gross Labour Cost (S\$)	2,220.00	1,560.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >