

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68682623
Accident Reporting Number : 68682672

Date Generated : 20/02/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHD6269L
Case Reference Number	TAX/02/23/2040
Registration Date	25/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEONG CHONG WAI
Type of Accident	Side Swipe
Accident Date and Time	18/2/23 2:40 PM
Accident Reported Date and Time	20/2/23 12:12 AM
Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24117668
Special Instruction to ARC, if any	LEFT REAR PORTION
Prepared Date and Time	20/2/23 2:12 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,296.00	\$0.00
Total Spare Part Cost	\$4,250.44	\$0.00
Total Other Cost	\$940.00	\$0.00
TOTAL COST	\$7,500.44	\$0.00
UMP Sum Total	\$7,500.00	\$0.00
Number of Repair Days	7.0	
Prepared / Adjusted By	Boon Chew Tay	3 days
ARC / Surveyor Sign Off Date	20/02/2023 10:30 AM	
Signature		 96910663
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

 SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68682623
 Accident Reporting Number : 68682672

Date Generated : 20/02/2023

User ID : munsan

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION LH	\$1,014.00	6001
total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	2001
O RESPRAY RIM	\$180.00	nn 2001 X
O RESPRAY REAR FENDER LH	\$378.00	2001
O RESPRAY FLOOR CORNER PANEL LH	\$180.00	nn X
O RESPRAY FUEL LID COVER	\$180.00	nn X
total Spray Painting & Panel Beating	\$1,296.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	X
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	201
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	301 601
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	nn X
O REMOVE AND REFIT TYRE	\$120.00	501
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	nn X
O REMOVE AND REFIX UNDERCARRIAGE	\$200.00	nn X
O REPLACE SUNDRY PARTS	\$100.00	nn X
total Other Costs	\$940.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	601 ✓
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80	Replace	nn X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	nn X
		81590-47070	LAMP ASSY, REAR, LH	1.00	\$317.80	10.00	\$286.02	Replace	nn X
		81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	1.00	\$282.70	10.00	\$254.43	Replace	nn X
		81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$367.30	10.00	\$330.57	Replace	nn X
		58399-47030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace	nn X
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$42.20	25.00	\$31.65	Replace	nn X
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	nn X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	nn ✓
		52592-47080	SEAL, RR BUMPER, LH	1.00	\$128.00	25.00	\$96.00	Replace	nn ✓
		52576-47060	RETAINER, RR BUMPER, LH	1.00	\$143.60	25.00	\$107.70	Replace	nn X
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	nn ✓
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	nn ✓
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	nn ✓
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	nn ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 20/02/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52462-47130	PAD, RR BUMPER, RH & LH . 3	2.00	\$12.00	25.00	\$18.00	Replace	<i>me ✓</i>
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	<i>me ✓</i>
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	<i>me X</i>
		61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	<i>me ✓</i>
		7735047050	LID ASSY, FUEL FILLER OPENING	1.00	\$164.10	25.00	\$123.07	Replace	<i>me X</i>
		65638-47060	LINER, REAR FENDER, LH	1.00	\$151.10	25.00	\$113.32	Replace	<i>me X</i>
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	<i>?</i>
Total					\$6,854.54		\$5,439.79		

Used Spare Parts / Material Usage After Surveyor Signed off

Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

*NOT WITHHOLD
1/1/2023*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: