



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23001868/Kqy3e2 Date: 10/03/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SNA 7310M	Veh. Inspected	SLG 6222H	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0565	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	20/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZVW506010136	Colour	METALLIC GREY	
Odometer	450659 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ARIVO	8 mm	
L/H Front Tyre	195/65 R15	ARIVO	8 mm	
R/H Rear Tyre	195/65 R15	ARIVO	9 mm	
L/H Rear Tyre	195/65 R15	ARIVO	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/02/2023	Inspection Date	20/02/2023	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 06 OCT 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	