

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Mar 23 2023
	Ticket No: LKK-J000057	Vehicle No: SLF2422D
	Policy No: 0	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Teo Yik Hon Vehicle: TOYOTA VOXY 2 X 2016 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 96402541 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	REAR BUMPER	Part	1.00	1,080.40	594.22	486.18	594.22	594.22
2	REAR BUMPER SIDE HOLDER LH	Part	1.00	98.50	54.17	44.33	54.17	54.18
3	TAILLAMP LOWER APRON	Part	1.00	385.10	211.81	173.29	211.81	211.81
4	SET REAR BUMPER CLIPS	Part	1.00	30.00	30.00	0.00	30.00	30.00
5	SET TAILLAMP LOWER APRON CLIPS	Part	1.00	20.00	20.00	0.00	20.00	20.00
							Taxable Value	910.20
							Discount Total	703.80
							Grand Total	910.21

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
6	PANEL BEATING, REMOVE AND REFIT PARTS	Labour	-	300.00	209.79	90.21	209.79	209.79
7	SPRAY PAINTING TO AFFECTED AREA	Labour	-	300.00	300.00	0.00	300.00	300.00
8	WIRING CHECK	Labour	-	30.00	30.00	0.00	30.00	30.00
9	TO REMOVE REVERSE SENSOR	Labour	-	50.00	50.00	0.00	50.00	50.00
							Taxable Value	589.79
							Discount Total	90.21
							Grand Total	589.79

					Parts Total	910.20
					Labour Total	589.79
					GST Total	0.00
					Grand Total	1,500.00
					Balance	1,500.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature