RECEY TENANT	Alg
<u> </u>	IGNMENT
Date:	Veh No: SJC4872P YT Regni: 2016 Dec
nated lost	Type: M. Dar / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
TP / WS X PRES / OD RES / EVA / TNV / MV	Truck / Trailer or
aspec/Vetalis No.	Melle: Hudi H3 0.0 1395
otketin um	Onbut Black 4/0: Instruct/Stille/NA
	Sp. Reading 73394 TiRedio: Insured Still No.
æĽ.	The server and place services assistant.
y No	Eng/No:
TIS N.	CANO: WANTELE & VIHIOISIAN Gen. Cond: Cool Febricon Burnt
i Insued: Exoses: Hon	
Senft Record	Sparings in office / Jermmed / Leaked / Burnit or Brates: Interfery Jermmed / Leaked / Burnit or
e of Vah:	Brais: inorrier/Jammed/Leaked/Burni or Modi: NU /BRm / STD ARRin or
hilloy Condition	Tyre 8tzs: 7: 205/55K/b
nanc The vehicle commencer to NS O/S	SS DUN EXPLOYA GT ST ST ST ST ST ST ST
repair side fine of inspection.	TOAD LADKO 'AL
or Market Value: \$681C.	Fron Resi
C Abstract 7 Consistant? : Yes or No	R/Szl. 6 mm R/Bel C mm
Consistent? : Yes or No	L/3al mm . L/Sal mm
n Sum: % 3 Val.: Yes or No	D.O.A. D.O.L. 20/2/23 Sitting bold at Premium Beno;
M	And to them of
. / REW / REP. / 24 HRS Vahide: IN / OU	Des. of Demages Tot I Rear I CIS NIS UIC Rooffop of
fe: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
ate /Time Action / Instruction	
Total loss, Not Execuon	nical forepar.
	<u> </u>
Time, File Pagg 40? Prelli. Report	Devin Of Bernalin
	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Addi	
	frantis (mienvieus 18

PREMIUM AUTOMOBILES



Premium Automobiles Pte Ltc

Telephone (65) 6566 1111

Telefax (65) 6471 3733

Telephone (65) 6336 2323

Telefax (65) 684 11183

Service & Parts Centres

Showroom

55 Ubi Rd 1 Singapore 408699

9 Leng Kee Road

Singapore 159090

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 The AIG Building Singapore 079120 Attn: Motor Claims Dept

Tel: 6419 1993

Your Ref: SJC 4872 P

Norah Khai 6768 9828 6841 1183 Nora.khai@premiumauto.com.sg

Body & Paint Dept PA/OD/TL01/2023

20 Feb 2022

Dear Sir/Mdm,

RE: ACCIDENT INVOLVING VEHICLE NO: SJC 4872 P VEHICLE MODEL: A4 SEDAN 1.0 TFSI S tronic

LOCATION: PIE TOWARD CHANGI ALONG TOA PAYOH

DOA: 19/1/2022

We refer to the vehicle mentioned above.

We have visually inspected the vehicle and would like to inform you that we have come to a conclusion that this vehicle is beyond economical repair.

The accident has caused intensive damages on the body of vehicle including unconfirmed damages. The damages incurred onto the whole frontal area, engine compartment bay, both front fender top, the engine and engine components, gearbox and airbag system which estimated to be \$\$125,851.20 for parts.

We also estimated labour cost to be \$\$45,700 before any supplementary. Kindly be informed that there will be possible additional damages not visible during inspection.

Thank you,

Norah Khai Claims Manager Tanphin 17495749 Drevent Ex: Ha 20/2/1504pm

LLK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No riegal medification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: