



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI23001921/Uwy3

Date: 21/02/2023

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 6289M	Veh. Inspected	SMZ 4974Y
Policy No.		Coverage (\$)	0.00
Claim No.	D23000663MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	21/02/2023

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	19/02/2023	Inspection Date	22/02/2023
Survey held at	330 UBI ROAD 3, SINGAPORE 408650		
Repairer	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.