	ASSIGNMENT
From: Date:	Veh No: SMQ 9958 J. Yr Regn: 2019, Dec
Estimated Cost:	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To In≲pect Vehicle No:	Make: Honda Vezel Hybrid . c.o 1496
et Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 167706. T/Radio: Insured / Std / NI / NA
nsur <i>e</i> d:	Eng/No:
Policy No.	C/No: R431320483 *
Claimas No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: norder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) STD A/Rim or
**	Tyre Size: F: 215/60R/6
(Policy Condition)	R: 215/60P/6
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
al. or Market Value:	<u>Front</u> <u>Rear</u>
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 26 mm R/Bal. 36 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
st. Repairs:days Res.: Yes or No	D.O.A. D.O.I. 23/02/23.
um Sum: % 3 Val.: Yes or No	Survey held at Jack Cars -
A / REV / REP. / 24 HRS	Des. of Damages Frt Rear O/S N/S U/C Rooftop or
Vehicle: I ate: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
OD Allianz	
1.0	
2071	
mv: 97K	
PV: 43.3K	
PV: 43.3K	A436
PV:43.3 K Nett: 53.7 K	0436.
PV: 43.3 K Nett: 53.7 K le/Time, File Pass to? : Prell. Report	0436. Days Of Repair:
PV: 43.3 K Nett: 53.7 K le/Time, File Pass to? : Preli. Report : Final Report	
PV: 43.3 C Neth: 53.7 C Ite/Time, File Pass to? : Preli. Report : Final Report te/Time, File Return to?	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
PV: 43.3 K Nett: 53.7 K te/Time, File Pass to? : Preli. Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee:



4.	"HONDA" EMBLEM Nu	\$ 95 /
	LABOUR	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 2500 60
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 2000 800
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 250 30
4.	TO REMOVE & REINSTALL SENSORS	\$ 200 7
5.	ANTI RUST TREATMENT	\$ 200 40
6.	PROGRAMMING (HEADLAMP & RADAR SENSOR)	\$ 700 ?
	PARTS + 10 %:	\$ 22,495
	SPECIAL NETT:	\$ 1,010
	LABOUR :	\$ 5,850
	TOTAL :	\$ 29,355
	8% GST :	\$ 2,348.40
	GRAND TOTAL :	\$ 31,703.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrim Lig h/s 23/02/23. 05 Days. Exum \$2k. Not Authorised.

A:3007 Ubi Road 1 #01-450 S(480701) T:67488824 F:67488834 W:www.jackcars.com.sg



ESTIMATE

DATE OF ACCIDENT: 16/02/2023

VEHICLE: SMQ9958J

MAKE & MODEL : HONDA VEZEL

INSURANCE: ALLIANZ

SURVEYOR: LKK ADRIAN

PARTS		AMOUNT
1.	BONNET Derted	\$ 2300
2.	BONNET INSULATOR NEW	\$ 210
3.	BONNET WEATHERSTRIP CH	\$ 330
4.	BONNET LOCK Dan d.	\$ 320 /
5.	BONNET HINGE - LEFT & RIGHT But	\$ 250 /
6.	FRONT FENDER - LEFT & Repris	\$ 980 🖈
7.	FRONT FENDER - RIGHT	\$ 980 &
8.	FRONT FENDER BRACKET - LEFT & RIGHT Wen	\$ 300 \(\chi \)
9.	HEADLIGHT-LEFT coucked.	\$ 2300 /
10.	HEADLIGHT - RIGHT No New	\$ 2300
11.	HEADLIGHT TOP BRACKET - RIGHT Not her	\$ 110+
12.	HEADLIGHT TOP BRACKET - LEFT ?	\$ 100 7
13.	HEADLIGHT LOWER BRACKET - RIGHT Al HU	\$ 110}



14.	HEADLIGHT LOWER BRACKET - LEFT 7	\$ 110 -2
15.	FRONT BUMPER Delid	\$ 900 /
16.	FRONT BUMPER CHROME GARNISH Could	\$ 350 —
17.	FRONT BUMPER GRILLE Crucd	\$ 520 /
18.	FRONT BUMPER GRILLE GARNISH and	\$ 380 -
19.	FRONT BUMPER LOWER GRILLE	\$ 410 ٢
20.	FRONT BUMPER LOWER LIPS Men	\$ 280 +
21.	FRONT BUMPER BRACKET - LEFT & RIGHT 2H 2 d	\$ 200- 10
22.	FRONT BUMPER SPONGE THE ME	\$ 180
23.	FOG LAMP MOTOR	\$ 690 +
24.	FOG LAMP COVER W	\$ 310 -
25.	INTAKE MANIFOLD KM M	\$ 2500~
26.	FRONT SUPPORT PANEL Pay	\$ 1800 🛠
27.	FRONT SUPPORT PANEL TOP COVER 7.	\$ 230 7
28.	FRONT SUPPORT BEAM BUT	\$ 690
29.	CENTRE BRACKET Could	\$ 310 /
	SPECIAL NETT	60
1.	REAR NUMBER PLATE & COVER But	\$-95
2.	CLIPS , RIVETS & SCREWS New	\$ 100 30
3.	RADAR SENSOR ?.	\$ 720 .

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	043G
Vehicle Details	THE RESIDENCE OF THE PARTY OF T
Vehicle No.:	SMQ9958J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	LEB6740494
Chassis No.:	RU31320483
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$28,358.00
Original Registration Date:	13 Dec 2019
First Registration Date:	13 Dec 2019
Transfer Count:	1
Actual ARF Paid:	\$21,702.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2029
PARF Rebate Amount:	\$16,276.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,728.00
COE Rebate Amount:	\$27,010.00
Total Rebate Amount:	\$43,286.00

The information contained herein is correct as at 24 Feb 2023

