



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23001971/Kny3
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)		Date:	22/02/2023
POLICE LOGISTICS BASE (PLB)			
1 HEMMANT ROAD SINGAPORE 438675		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 1930G	Veh. Inspected	SND 1242A
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/007	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	21/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	13/01/2023	Inspection Date	22/02/2023
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			