



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23001972/Kny3m4 Date: 17/03/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 3273Z	Veh. Inspected	SJG 5701Y
Policy No.		Coverage (\$)	0.00
Claim No.	D23000651MFVS	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	21/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305070723	Colour	METALLIC GOLD
Odometer	355092 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60R15	MICHELIN	9 mm
L/H Front Tyre	185/60R15	MICHELIN	9 mm
R/H Rear Tyre	185/60R15	MICHELIN	9 mm
L/H Rear Tyre	185/60R15	MICHELIN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/02/2023	Inspection Date	27/02/2023
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	