

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06767

Vehicle Insured : XE3273Z
Accident Date : 20-Feb-2023

Date : 21-Feb-2023

Our Ref : 023040 (FIRST) / CHAN

PAGE : 1

KASNI BIN MASKIDAM
BLK 165 WOODLANDS STREET 13
#09-561
Singapore 730165

Not Authorized
11 Rm @ 2950/hr
Recovery After Pains
5 days

ESTIMATED COST OF REPAIR FOR TOYOTA VIOS SJG5701Y

=====

1 pc Rear o/s door
1 pc Rear o/s door outer handle
1 pc Rear o/s door rubber
1 pc Rear o/s door inner lock
1 pc Rear o/s door protector
1 pc O/s door protector chrome
1 pc Rear o/s door glass regulator
gear
1 pc Rear o/s door glass regulator
motor
1 pc Rear o/s fender
1 pc Rear w/s glass moulding
1 pc O/s side skirt

R 1,122.70 ✓
D/I 78.70 ✓
R 215.00 X
nd/m 592.80 ✓
R 109.90 ✓
R 26.90 ✓
D/I 194.80 ✓
Tm 765.50 ✓
R 1,250.20 X
nn 97.40 X
cm 368.80 ✓

4,822.70

Less 25% : 1,205.68

3,617.02
nn 60.00 *sn* X

1 pc Rear w/s glass selant

To remove & refix rear windscreen
glass and conduct water leak test.

nn 150.00 X

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

60.00 *301*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3273Z

Page : 2

To putty and spray replaced parts

500
700.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 *680*

Total : S\$ 5,507.02
=====

Singapore Dollars Five Thousand Five Hundred
and Seven and Cents Two Only