



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 21/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	18/07/2017	SLQ6315X	0	20311	75/DS/SLQ6315X
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU903562198	2ZRS058258	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:WC5617A ACC DATE:21/02/23 TOW IN:21/02/23 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				638.00
5	B	BP-RES2 RESPRAY ACC AFF AREA				524.00
6	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#)				80.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
8	B	BP-MECH2 R/I AIRCON CONDENSER				1584.00
9	1	U52119-47962 COVER, FR BUMPER	1.00	622.20		622.20
10	2	U52114-47190 BRACKET, FR BUMPER	1.00	124.10		124.10
11	3	U53112-47240 GRILLE, RADIATOR	1.00	204.20		204.20
12	4	U53395-47040 SEAL, HOOD TO FR END	1.00	62.00		62.00
13	5	U52115-47050 SUPPORT, FR BUMPER	1.00	95.70		95.70
14	6	U52116-47050 SUPPORT, FR BUMPER	1.00	95.70		95.70

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 21/02/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	18/07/2017	SLQ6315X	0	20311	75/DS/SLQ6315X

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU903562198	2ZRS058258	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	7	U52161-16010	PIECE, RR BUMPER	10.00	5.40	54.00
16	8	U52127-47907	COVER, FR BUMPER	1.00	35.30	35.30
17	9	U52128-47906	COVER, FR BUMPER	1.00	35.30	35.30
18	0	U52618-47090	ABSORBER, FR BUMPER	1.00	159.40	159.40
19	1	U52611-47140	ABSORBER, FR BUMPER	1.00	95.40	95.40
20	2	U52132-47010	REINFORCEMENT, FR	1.00	295.20	295.20
21	3	U52102-47020	EXTENSION SUB-ASSY,	1.00	144.20	144.20
22	4	U52103-47010	EXTENSION SUB-ASSY,	1.00	144.20	144.20
23	5	U52021-47110	REINFORCEMENT	1.00	859.20	859.20
24	6	U53101-47081	GRILLE SUB-ASSY,	1.00	415.60	415.60
25	7	U53301-47110	HOOD SUB-ASSY	1.00	1184.00	1184.00
26	8	T53341-47041	INSULATOR, HOOD	1.00	493.40	493.40
27	9	U53801-47080	FENDER SUB-ASSY, FR	1.00	1177.80	1177.80
28	0	U53802-47100	FENDER SUB-ASSY, FR	1.00	1177.80	1177.80
29	1	U53827-47050	PROTECTOR, FR FENDER	1.00	113.00	113.00
30	2	U53828-47070	PROTECTOR, FR FENDER	1.00	113.00	113.00
31	3	U53807-47020	SEAL SUB-ASSY,	1.00	62.40	62.40
32	4	U53808-47020	SEAL SUB-ASSY,	1.00	62.40	62.40
33	5	U53875-47070	LINER, FR FENDER, RH	1.00	248.10	248.10
34	6	U53876-47110	LINER, FR FENDER, LH	1.00	243.20	243.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	4264.10
			Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 21/02/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	18/07/2017	SLQ6315X	0	20311	75/DS/SLQ6315X
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU903562198	2ZRS058258	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	7	U53510-47140 LOCK ASSY, HOOD <i>? xan</i>	1.00	162.20		162.20
36	8	U85315-47160 JAR, WASHER, A <i>mir</i>	1.00	263.00		263.00
37	9	U85319-47170 PIPE, WASHER, A <i>mir</i>	1.00	80.20		80.20
38	0	U53289-47072 COVER, RADIATOR <i>? xan</i>	1.00	282.80		282.80
39	1	U16592-37020 GUIDE, RADIATOR AIR, <i>? xan</i>	1.00	135.60		135.60
40	2	U53202-47901 SUPPORT S/A, <i>? xan</i>	1.00	294.20		294.20
41	3	U53205-47900 SUPPORT S/A, <i>? xan</i>	1.00	453.60		453.60
42	4	U53217-47030 BRACE, HOOD LOCK <i>? xan</i>	1.00	93.60		93.60
43	5	U53203-47901 SUPPORT S/A, <i>? xan</i>	1.00	294.20		294.20
44	6	U53028-47010 SUPPORT SUB-ASSY, <i>? xan</i>	1.00	492.50		492.50
45	7	U53701-47111 APRON SUB-ASSY, FR <i>? xan</i>	1.00	1178.00		1178.00
46	8	U53702-47101 APRON SUB-ASSY, FR <i>? xan</i>	1.00	1178.00		1178.00
47	9	U81145-47691 UNIT, HEADLAMP <i>cm</i>	1.00	3167.20		3167.20
48	0	U81185-47691 UNIT, HEADLAMP <i>cm</i>	1.00	3167.20		3167.20
49	1	T81210-47020 LAMP ASSY, FOG, RH <i>cm</i>	1.00	1143.60		1143.60
50	2	U81220-47020 LAMP ASSY, FOG, LH <i>cm</i>	1.00	1143.60		1143.60
51	3	U75310-47060 EMBLEM ASSY, <i>ny</i>	1.00	109.50		109.50
52	4	U75374-47140 EMBLEM, SIDE PANEL <i>m</i>	1.00	65.60		65.60
53	5	U75374-47150 EMBLEM, SIDE PANEL <i>m</i>	1.00	65.60		65.60
54	6	U51420-47030 COVER ASSY, ENGINE <i>xan</i>	1.00	223.20		223.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 36,254.20
IRK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	Please acknowledge receipt of vehicle	Parts 22,310.20 Labour 13,864.00 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 8.00% 2,900.34 Less 0.00 Amount Due 39,154.54

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No. S1000019 / ICUOI1		Customer Details				
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		Document No. 0		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925				
		Document Date 03/03/2023						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	18/07/2017	SLQ6315X	0	20311	75/DS/SLQ6315X	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU903562198		2ZRS058258	60	Ng Mei Yen	23/02/2023 8.00		28/02/2023 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	U90980-12A92 HOUSING, CONNECTOR <i>mis</i>			1.00	36.30		36.30
2	2	T85330-47100 MOTOR & PUMP ASSY, <i>mis</i>			1.00	351.30		351.30
3	3	U85348-14390 JOINT <i>mis</i>			1.00	7.50		7.50
4	4	U90099-33080 TUBE, RUBBER <i>mis</i>			1.00	20.30		20.30
5	5	T90099-33080 TUBE, RUBBER <i>mis</i>			1.00	20.30		20.30
6	6	U90467-07214 CLIP <i>mis</i>			10.00	3.20		32.00
7	7	U90467-07217 CLIP <i>mis</i>			10.00	3.00		30.00
8	8	S85375-02330 JOINT, WASHER, D <i>mis</i>			2.00	5.30		10.60
					508.30			
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		508.30
		Please acknowledge receipt of vehicle		Parts		GST 8.00%		40.66
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others				
				Less		0.00		
				Amount Due		548.96		

Customer Copy