

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 24 Mar 2023

**Preliminary Advice**

Vehicle No	: SMJ4497S	Accident Date	: 21/02/2023
Make	: KIA CARENS	Policy No.	: SP2002451400
Assignment Date	: 23/02/2023	Excess	: S\$2,000.00
Date of Inspection	: 24/02/2023	Est. Duration of Repair	: 10
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 60 JALAN LAM HUAT CARROS CENTRE, #07-43 SINGAPORE 737869		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,566.60	(Estimate \$12,513.80 + Supplementary \$52.80)
Revised Amount	:S\$	8,311.40	
Check Items (Estimated)	:S\$	1,695.90	
Total	:S\$	10,007.30	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	36,243.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,757.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.