

Immediate Advice

To: AXA Insurance Pte Ltd 9/3/2023

Survey Details:

Date of loss	18-Feb-23
Date of appointment	23-Feb-23
Date of survey	27-Feb-23
Location of survey	SPEEDWERKZ PTE LTD

Vehicle Details:

Claim Type:	Third Party Claim	
Vehicle number	GBK 5876A	
Make and Model	TOYOTA HIACE DX 2.8 AUTO	
Date of registration	16/9/2020	
Excess	-	
Market Value	\$ 80,000.00	
Parf Rebate	\$ 18,885.00	
Nett Loss	\$ 61,115.00	

Repair details:

Initial Estimate	\$	24,529.64
	τ	,

Proposed/Revised repair cost:

Lump Sum(if applicable)	\$ 1,800.00
Total	\$ 2,269.12
Labour	\$ 900.00
Check items (estimate)	\$ -
Parts	\$ 1,369.12

Number of days for repair	<u>3</u>



51 UBI AVE 1, #91-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Damages consistent.		

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	