

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS/HSB2300204/Uq23

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 6B1K5876Aat Workshop m/s Spaworth

of _____

Insured: SKU8408R

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$80K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C727E

Vehicle: IN / OUT

Date: _____ Person Contacted: L7A51888Veh No: 6B1K5876AYr Regn: 16/09/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: ToyotaColour: SilverSp. Reading: 94867

Eng/No: _____

C/No: GDM2011037124Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/02/23

Survey held at _____

Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/3/23 4/5 \$1800 in hand (not used \$22729.64, 93%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/3/23☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : Smart claims-TPLump Sum / I.B.F. (\$) 1800

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 , #01-73 , AUTOBAY , SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER : GBD5876A
MAKE & MODEL: TOYOTA HIACE
DOA: 18/2/2023
CLAIM TYPE: TP CLAIM

Not Authorised
27/2/23
2/s\$1800/
3 days.
4/s\$1800

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$1,217.00	11 X
FRONT BONNET EMBLEM	1	\$73.50	11 X
FRONT BONNET HINGE @83.60	2	\$167.50	11 X
FRONT BONNET LOCK	1	\$125.44	11 X
FRONT GRILLE	1	\$1,211.70	one ✓
FRONT GRILLE TOP COVER	1	\$64.12	11 X
FRONT FRILLE CENTRE GARNISH	1	\$286.00	11 X
FRONT SUPPORT PANEL	1	\$667.52	R X
FRONT HEAD LAMP @1150	2	\$2,300.00	11 X
FRONT HEAD LAMP PANEL @215.50	2	\$431.00	11 X
FRONT BUMPER Sport	1	\$1,295.00	10/20 ✓
FRONT BUMPER LOWER GRILLE	1	\$109.48	11 X
FRONT BUMPER SIDE AIR GRILLE @77.00	2	\$154.00	11 X
FRONT BUMPER REINFORCEMENT BRACKET @112.00	2	\$224.00	11 X
FRONT BUMPER REINFORCEMENT	1	\$460.40	R X
FRONT BUMPER SIDE RETAINER @233.52	2	\$467.04	11 X
FRONT BUMPER TOP BEAM	1	\$213.22	11 X
FRONT AIR DUCT	1	\$223.58	11 X
AIR CLEANER BOX ASSY	1	\$1,081.78	11 X
AIR COND CONDENSER	1	\$1,675.66	11 X
RADIATOR	1	\$2,500.26	11 X
TURBO COOLER	1	\$1,245.00	11 X
TURBO COOLER COWLING	1	\$82.04	11 X
RADIATOR FAN COWLING (BIG)	1	\$385.28	11 X
RADIATOR FAN ASSY	1	\$1,911.28	11 X
AIRCOND DISCHARGE HOSE	1	\$276.00	11 X
AIRCOND LIQUID PIPE	1	\$215.30	11 X
RADIATOR SPARE TANK	1	\$371.28	11 X
RADIATOR TOP BRACKET @91.28	2	\$182.56	11 X
WIPER WASHER TANK	1	\$371.70	11 X
FRONT CORNER PANEL @252.90	2	\$505.80	11 X
FRONT WIPER GRILLE	1	\$679.70	11 X
BRAKE BOOSTER	1	\$1,859.30	11 X
BRAKE MASTER PUMP	1	\$906.08	11 X

\$23,939.52

Less 25 % \$5,984.88

Sub Total \$17,954.64

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT GRILLE CLIP	1	\$50.00	11 X

FRONT NUMBER PLATE	1	\$45.00	8u X
Sub Total		<u>\$95.00</u>	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$100.00	20
APPLY ANTI RUST CHEMICAL		\$150.00	11 X
LABOUR CHARGE KNOCK DENTS, WELDING AND RENEW PART		\$3,500.00	400
TO SPRAY PAINT AFFECTED PORTION		\$2,500.00	480
REMOVE AND REFIX RADIATOR		\$80.00	11 X
REMOVE AND REFIX RENEW AIRCON CONDENSER AND REFILL GAS		\$150.00	11 X
Sub Total		<u>\$6,480.00</u>	

Grand Total \$24,529.64

7-1825.49
 252
 1369.11
 900
 2269.11
 202
 1815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: