

Huey Yon (LKKAuto)

---

**From:** Huey Yon (LKKAuto)  
**Sent:** Wednesday, 1 March 2023 9:23 AM  
**To:** peiyi@sme.com.sg  
**Cc:** SUR  
**Subject:** CHINA-OD SMK 8251C DOA: 18/02/2023

Dear Pei Yi,

As instructed by our client, please proceed to repair the insured vehicle **SMK 8251C at repair cost not more than lump sum \$13,000.00 (Excess \$0/-)**.

Kindly arrange our surveyor to take after paint photos before release the vehicle to owner.

If there are any check items or supplementary items please inform our office’s Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Huey Yon** | case handler  
**LKK Auto Consultants Pte.Ltd.**  
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933