

(08/11/13) Wef

REF:

CS/CT123002051/Rp3

6803

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: FBT 3612K

at Workshop m/s WEARNBS

of 45, LENT KEE RD

Insured:

CTI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

28K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBT 3612K

Yr Regn: 2022 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

DUCATI SCRAMBLER D.S

c.c 803

Colour

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

5248

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ML6SK500AA MT000169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIP / S/Rim / STD A/Rim or

Tyre Size:

F:

120 / 70 R19

R:

120 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

01/02/23

D.O.I.

23/02/23

Survey held at

WEARNBS

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 19K

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Service Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. : 0 Page 1
Inv.date : 21/02/2023
WIP No. : 61395
Veh. In/Out:
*Tel.No. : Mobile: 90297954
Reg.No. : FBT3612K / SCR
Reg.date : 25/01/2022
Mileage : 0
Chassis No. : ML05K00AAMT000169
Variant : SCR Desert Sled

No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
UCT-A	Accident Damage Assessment				70.00	0		70.00	S
UCO-1	To replace damaged parts caus	BT			4500.00	10	(over)	4050.00	S
81	Number plate				0.01	0		0.01	S
	SIDE STAND SCR			1.0 EA	248.30	20		198.64	S
	COMPLETE SPRING X			1.0 EA	33.00	20		26.40	S
	INNER SPRING X			1.0 EA	9.50	20		7.60	S
	LINK, SIDE STAN X			1.0 EA	9.80	20		7.84	S
	NUT X			1.0 EA	3.00	20		2.40	S
	AXLE, SIDE STAN X			1.0 EA	12.50	20		10.00	S
	SCREW X			1.0 EA	2.70	20		2.16	S
	SWITCH, STAND #?			1.0 EA	126.60	20		101.28	S
	SCREW TBEIF M10 X			1.0 EA	9.60	20		7.68	S
	BRACKET, SIDE S X			1.0 EA	165.60	20		132.48	S
	SPACER X			1.0 EA	3.10	20		2.48	S
	SCREW Y			1.0 EA	9.10	20		7.28	S
	SCREW X			1.0 EA	3.60	20		2.88	S
	LOWER CHAIN SLI X			1.0 EA	18.00	20		14.40	S
	STAY COMP. ?			1.0 EA	427.60	20		342.08	S
	NUT, SPRING M5 ?			1.0 EA	4.10	20		3.28	S
	SPACER ?			1.0 EA	2.80	20		2.24	S
	SCREW, SPECIAL ?			1.0 EA	1.20	20		0.96	S
	CUSHION, SEAT SCR			1.0 EA	2.50	20		2.00	S
	SCREW ?			1.0 EA	1.10	20		0.88	S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Cu Reg No: 199501400R / GST Reg. No.: M28920628X

SERVICE ESTIMATE

09416 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Yap Bing Liang, Casper
k 109 Serangoon North Avenue 1
4-651

ngapore 550109

osed by : Michael Tan Yuh Ling
c Consultant : Michael Tan Yuh Ling
marks : Mr Yap Bing Liang, C

Inv.No. ... : 0 0 Page 2
Inv.date ... : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:
*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date ... : 25/01/2022
Mileage ... : 0
Chassis No.: ML05K00AAMT000169
Variant... : SCR Desert Sled

No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	COVER <i>cm</i>			1.0 EA	16.80	20		13.44	S
	REFLEX REFLECTO <i>scr</i>			1.0 EA	6.30	20		5.04	S
	NUT, SPRING ?			1.0 EA	0.30	20		0.24	S
	WASHER 4.5X9X0. ?			1.0 EA	1.50	20		1.20	S
	PLATE HOLDER X			1.0 EA	29.40	20		23.52	S
	LAMP, LICENSE P <i>scr</i>			1.0 EA	76.90	20		61.52	S
	VIBRATION DAMPE <i>m</i>			1.0 EA	27.10	20		21.68	S
	SCREW ?			1.0 EA	1.30	20		1.04	S
	SCREW ?			1.0 EA	1.40	20		1.12	S
	TOOTHED LOCK WA ?			1.0 EA	0.30	20		0.24	S
	SCREW TCEIF M8X ?			1.0 EA	4.50	20		3.60	S
	SCREW TBEIF M6X ?			1.0 EA	2.90	20		2.32	S
	WASHER ?			1.0 EA	0.80	20		0.64	S
	CLAMP ?			1.0 EA	0.50	20		0.40	S
	PLUG ?			1.0 EA	12.50	20		10.00	S
	REAR-VIEW MIRRO <i>scr</i>			1.0 EA	166.50	20		133.20	S
	LEFT COVER <i>scr</i>			1.0 EA	14.40	20		11.52	S
	SPACER ?			1.0 EA	41.40	20		33.12	S
	VALVE, BREATHER ?			1.0 EA	2.10	20		1.68	S
	PISTON ASSEMBLY ?			1.0 EA	260.80	20		208.64	S
	DUST COVER ?			1.0 EA	32.50	20		26.00	S
	CLUTCH MASTER C ?			1.0 EA	510.20	20		408.16	S
	BRACKET, CLUTCH ?			1.0 EA	28.10	20		22.48	S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X

Occupation

Accident report SW0923220000

Page 1 of 17



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. ... : D 0 Page 3
Inv.date .. : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:
*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date .. : 25/01/2022
Mileage ... : 0
Chassis No.: ML05K00AAMT000169
Variant... : SCR Desert Sled

No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	CLUTCH CONTROL ?			1.0 EA	112.00	20		89.60	S
	GASKET ? ?			1.0 EA	3.80	20		3.04	S
	MICROSWITCH ?			1.0 EA	147.40	20		117.92	S
	BOLT, BRAKE HOS ?			1.0 EA	20.20	20		16.16	S
	WASHER 10X14X1 ?			1.0 EA	0.50	20		0.40	S
	SCREW TCEIR M6X ?			1.0 EA	0.50	20		0.40	S
	BOLT, PIVOT ?			1.0 EA	13.80	20		11.04	S
	CLUTCH LEVER ?			1.0 EA	216.60	20		173.28	S
	PLUG ASSY ?			1.0 EA	92.60	20		74.08	S
	SCREW, SPECIAL ?			1.0 EA	22.60	20		18.08	S
	SCREW ?			1.0 EA	1.00	20		0.80	S
	SPACER ?			1.0 EA	18.00	20		14.40	S
	RUBBER PAD ?			1.0 EA	2.50	20		2.00	S
	FRONT MUDGUARD ?			1.0 EA	281.80	20		225.44	S
	BRACE, FRONT FE ?			1.0 EA	51.60	20		41.28	S
	RUBBER PAD ?			1.0 EA	6.00	20		4.80	S
	SCREW ?			1.0 EA	7.40	20		5.92	S
	RIGHT COVER X ?			1.0 EA	34.50	20		27.60	S
	PROTECTION, LEE ?			1.0 EA	34.50	20		27.60	S
	SCREW, SPECIAL ?			1.0 EA	1.20	20		0.96	S
	BRACKET, BRAKE ?			1.0 EA	49.70	20		39.76	S
	FRONT L.H. PLAT ?			1.0 EA	123.30	20		98.64	S
	SCREW ?			1.0 EA	4.60	20		3.68	S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X

Occupation

SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Inv.No. ... : D 0 Page 4
Inv.date ... : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:

Singapore 550109

*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date ... : 25/01/2022
Mileage ... : 0
Chassis No.: ML05K00AAMT000169
Variant... : SCR Desert Sled

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	SCREW TCEIF M6X ?			1.0 EA	3.00	20		2.40	S
	GEAR CONTROL LE ?			1.0 EA	49.70	20		39.76	S
	SCREW TCEIF M6X ?			1.0 EA	2.50	20		2.00	S
	ROD, GEAR SHIFT ?			1.0 EA	73.20	20		58.56	S
	PIN PEDAL ne ✓			1.0 EA	10.20	20		8.16	S
	GEARCHANGE LEVE 4 ✓			1.0 EA	102.60	20		82.08	S
	RUBBER PAD ne ✓			1.0 EA	3.40	20		2.72	S
	PLUG ?			1.0 EA	3.80	20		3.04	S
	O-RING ?			1.0 EA	0.40	20		0.32	S
	WASHER ?			1.0 EA	1.30	20		1.04	S
	CIRCLIP E-TYPE ?			1.0 EA	1.00	20		0.80	S
	FOOTREST PIN ?			1.0 EA	9.90	20		7.92	S
	SPRING, FOOTRES ?			1.0 EA	3.30	20		2.64	S
	LEFT FOOTREST SCR ✓			1.0 EA	45.20	20		36.16	S
	FOOT PEG RUBBER ne ✓			1.0 EA	13.40	20		10.72	S
	LEFT FOOTREST SCR ✓			1.0 EA	118.80	20		95.04	S
	REAR L.H. PLATE ?			1.0 EA	96.60	20		77.28	S
	SPRING RETAINER ?			1.0 EA	7.10	20		5.68	S
	SPRING ?			1.0 EA	1.60	20		1.28	S
	BALL ?			1.0 EA	0.60	20		0.48	S
	HEEL GUARD L.H. ?			1.0 EA	38.70	20		30.96	S
	SCREW ?			1.0 EA	1.10	20		0.88	S
	NUT, SELF-LOCKI ?			1.0 EA	0.40	20		0.32	S

SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, CInv.No. : 0 0 Page 5
Inv.date : 21/02/2023
WIP No. : 61395
Veh. In/Out:
*Tel.No. : Mobile: 90297954
Reg.No. : FBT3612K / SCR
Reg.date : 25/01/2022
Mileage : 0
Chassis No. : ML05K00AAMT000169
Variant : SCR Desert Sled

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount G
	FLASHER LIGHT <i>SCR</i>	1.0 EA	107.40	20		85.92 S
	FLASHER LIGHT <i>X</i>	1.0 EA	107.40	20		85.92 S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
2 days
P/P
23/02/23 @ 1640
Resy before rep

			Amount	7,624.73
Labour Total	4,120.01	Amount	7,624.73	
Parts Total	3,504.72	GST @ 8%	609.98	
Package Total	0.00	Total Amount	8,234.70	
			Less Amt Paid	0.00
			Nett Amount	8,234.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Service Estimates are valid for 10 days from the above date.

This is a computer generated invoice, no signature is required.

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X

Occupation

(E)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	680J
Vehicle Details	
Vehicle No.:	FBT3612K
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2023
Vehicle Make:	DUCATI
Vehicle Model:	SCRAMBLER DESERT SLED
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	DPT800A2H914490
Chassis No.:	ML05K00AAMT000169
Maximum Power Output:	-
Open Market Value:	\$11,256.00
Original Registration Date:	25 Jan 2022
First Registration Date:	25 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$4,506.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$10,000.00
COE Rebate Amount:	\$8,911.00
Total Rebate Amount:	\$8,911.00