

(08/11/13) wef

ASS. REC. BY: James

REF:

CS/CT123002051/Rp3

6803

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBT 3612Kat Workshop m/s WEARNSof 45, LEM KEE RD

Insured:

CTI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

28K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time Action / Instruction

REPAIR LIMIT - 19K

Basul confirmed final fig \$4999.20 with 2 days
(Red, \$2625.53, 34%)

Veh No:

FBT 3612K

Yr Regn: 2022 JAU

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

DUCATI SCRAMBLER D.S

c.c 803

Colour

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

5248

T/Radio: Insured / Std / NI / NA

Eng/No:

ML6SK50AAMT000169

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70R19

R:

170/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

01/02/23

D.O.I.

23/02/23

Survey held at

WEARNS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/02/2023 18:00 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	01/02/2023 10:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SINGAPORE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBT3612K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Yap Bing Liang, Casper
NRIC No	SXXXX680J
Email Address	casperyap@gmail.com
Mobile Phone No	(Phone) +65-90297954
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Ducati
Model	SCRAMBLER DESERT SLED
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Auto
CC	803

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V01907

DRIVER

Name of Driver	Yap Bing Liang, Casper
NRIC No	SXXXX680J
Date Of Birth	11/03/1988
Occupation	Outdoor

Date Of Driving Pass	28/03/2016
Driving experience	6 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90297954
Alt. Phone Number	-
Email Address	casperyap@gmail.com
Address	Blk 109 Serangoon North Avenue 1 #04-651
Address complement	-
Postcode	550109
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8690A
Vehicle Manufacturer	Isuzu
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TAI SOON PENG
NRIC No	SXXXX675I

Contact Number	(Phone) +65-98311561
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

WITNESS DETAILS

WITNESS 1

Name	HAIKAL
Phone	(Phone) +65-98215065
Email	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 1/2/2023

504 pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 10am, I received a call informing me that my bike has dropped. According to witness [HAIKAL, H/P: 93215065] ST Logistic lorry driver TAN Soon Peng was driving in and wanted to make a right turn and his left side of his lorry clipped my bike right side handle bar and dragged my bike a bit and till the side stand close back up and it dropped.

Vehicle A: DUCATI SERAMBIER desert sled: FB3612K
Vehicle B: ISUZU GREEN LORRY: YP3690A

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 11/21/2023 5:04pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. : 0 Page 1
Inv.date : 21/02/2023
WIP No. : 61395
Veh. In/Out:
*Tel.No. : Mobile: 90297954
Reg.No. : FBT3612K / SCR
Reg.date : 25/01/2022
Mileage : 0
Chassis No. : ML05K00AAMT000169
Variant : SCR Desert Sled

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
			70.00	0	XM ?	70.00	S
DUCT-A	Accident Damage Assessment		4500.00	10	1000	4050.00	S
DUCO-1	To replace damaged parts caus	BT	0.01	0	45	0.01	S
281	Number plate		248.30	20	260.80	198.64	S
	SIDE STAND	1.0 EA	33.00	20		26.40	S
	COMPLETE SPRING	1.0 EA	9.50	20		7.60	S
	INNER SPRING	1.0 EA	9.80	20		7.84	S
	LINK, SIDE STAN	1.0 EA	3.00	20		2.40	S
	NUT	1.0 EA	12.50	20		10.00	S
	AXLE, SIDE STAN	1.0 EA	2.70	20		2.16	S
	SCREW	1.0 EA	126.60	20		101.28	S
	SWITCH, STAND	1.0 EA	9.60	20		7.68	S
	SCREW TBEIF M10	1.0 EA	165.60	20		132.48	S
	BRACKET, SIDE S	1.0 EA	3.10	20		2.48	S
	SPACER	1.0 EA	9.10	20		7.28	S
	SCREW	1.0 EA	3.60	20		2.88	S
	SCREW	1.0 EA	18.00	20		14.40	S
	LOWER CHAIN SLI	1.0 EA	427.60	20	449	342.08	S
	STAY COMP.	1.0 EA	4.10	20	4.10	3.28	S
	NUT, SPRING M5	1.0 EA	2.80	20	2.80	2.24	S
	SPACER	1.0 EA	1.20	20	1.20	0.96	S
	SCREW, SPECIAL	1.0 EA	2.50	20	2.50	2.00	S
	CUSHION, SEAT	1.0 EA	1.10	20	4.40	0.88	S
	SCREW						

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. ... : D 0 Page 2
Inv.date ... : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:
*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date ... : 25/01/2022
Mileage ... : 0
Chassis No. : ML05K00AAMT000169
Variant... : SCR Desert Sled

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	COVER <i>cm</i>	1.0	EA		16.80	20		16.80	13.44 S
	REFLEX REFLECTO <i>scr</i>	1.0	EA		6.30	20		6.90	5.04 S
	NUT, SPRING <i>? nu</i>	1.0	EA		0.30	20		0.30	0.24 S
	WASHER 4.5X9X0. <i>? nu</i>	1.0	EA		1.50	20		1.50	1.20 S
	PLATE HOLDER <i>X n</i>	1.0	EA		29.40	20			23.52 S
	LAMP, LICENSE P <i>scr</i>	1.0	EA		76.90	20		76.90	61.52 S
	VIBRATION DAMPE <i>nu</i>	1.0	EA		27.10	20		108.40	21.68 S
	SCREW <i>? X n</i>	1.0	EA		1.30	20			1.04 S
	SCREW <i>? X n</i>	1.0	EA		1.40	20			1.12 S
	TOOTHED LOCK WA <i>? nu</i>	1.0	EA		0.30	20		1.20	0.24 S
	SCREW TCEIF M8X <i>? nu</i>	1.0	EA		4.50	20		4.50	3.60 S
	SCREW TBEIF M6X <i>? nu</i>	1.0	EA		2.90	20		2.90	2.32 S
	WASHER <i>? nu</i>	1.0	EA		0.80	20		0.80	0.64 S
	CLAMP <i>? nu</i>	1.0	EA		0.50	20		0.50	0.40 S
	PLUG <i>? nu</i>	1.0	EA		12.50	20		12.50	10.00 S
	REAR-VIEW MIRRO <i>scr</i>	1.0	EA		166.50	20		166.50	133.20 S
	LEFT COVER <i>scr</i>	1.0	EA		14.40	20		14.40	11.52 S
	SPACER <i>? nu</i>	1.0	EA		41.40	20		43.50	33.12 S
	VALVE, BREATHER <i>? nu</i>	1.0	EA		2.10	20		2.10	1.68 S
	PISTON ASSEMBLY <i>? nu</i>	1.0	EA		260.80	20		260.80	208.64 S
	DUST COVER <i>? scr</i>	1.0	EA		32.50	20		32.50	26.00 S
	CLUTCH MASTER C <i>? nu</i>	1.0	EA		510.20	20		535.70	408.16 S
	BRACKET, CLUTCH <i>? nu</i>	1.0	EA		28.10	20		28.10	22.48 S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. ... : D 0 Page 3
Inv.date ... : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:
*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date ... : 25/01/2022
Mileage ... : 0
Chassis No. : ML05K00AAMT000169
Variant... : SCR Desert Sled

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
	CLUTCH CONTROL ? new	1.0 EA	112.00	20		117.60	89.60 S
	GASKET ? new	1.0 EA	3.80	20		3.80	3.04 S
	MICROSWITCH ? new	1.0 EA	147.40	20		154.70	117.92 S
	BOLT, BRAKE HOS ? new	1.0 EA	20.20	20		20.20	16.16 S
	WASHER 10X14X1 ? new	1.0 EA	0.50	20		0.50	0.40 S
	SCREW TCEIR M6X ? new	1.0 EA	0.50	20		0.50	0.40 S
	BOLT, PIVOT ? new	1.0 EA	13.80	20		13.80	11.04 S
	CLUTCH LEVER ? new	1.0 EA	216.60	20		216.60	173.28 S
	PLUG ASSY ? new	1.0 EA	92.60	20		92.60	74.08 S
	SCREW, SPECIAL ? new	1.0 EA	22.60	20		22.60	18.08 S
	SCREW ? new	1.0 EA	1.00	20		1.00	0.80 S
	SPACER ? new	1.0 EA	18.00	20		18.90	14.40 S
	RUBBER PAD ? new	1.0 EA	2.50	20		2.50	2.00 S
	FRONT MUDGUARD ? new	1.0 EA	281.80	20		295.90	225.44 S
	BRACE, FRONT FE ? new	1.0 EA	51.60	20		55.40	41.28 S
	RUBBER PAD ? new	1.0 EA	6.00	20		6.00	4.80 S
	SCREW ? new	1.0 EA	7.40	20		7.40	5.92 S
	RIGHT COVER ? new	1.0 EA	34.50	20			27.60 S
	PROTECTION, LEE ? new	1.0 EA	34.50	20		36.30	27.60 S
	SCREW, SPECIAL ? new	1.0 EA	1.20	20		1.20	0.96 S
	BRACKET, BRAKE ? new	1.0 EA	49.70	20		52.80	39.76 S
	FRONT L.H. PLAT ? new	1.0 EA	123.30	20		129.40	98.64 S
	SCREW ? new	1.0 EA	4.60	20		4.80	3.68 S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X



SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. ... : D 0 Page 4
Inv.date ... : 21/02/2023
WIP No. ... : 61395
Veh. In/Out:
*Tel.No. ... : Mobile: 90297954
Reg.No. ... : FBT3612K / SCR
Reg.date ... : 25/01/2022
Mileage ... : 0
Chassis No. : ML05K00AAMT000169
Variant... : SCR Desert Sled

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
	SCREW TCEIF M6X ? <i>new</i>	1.0 EA	3.00	20		3.00	2.40 S
	GEAR CONTROL LE ? <i>new</i>	1.0 EA	49.70	20			39.76 S
	SCREW TCEIF M6X ? <i>new</i>	1.0 EA	2.50	20		2.50	2.00 S
	ROD, GEAR SHIFT ? <i>new</i>	1.0 EA	73.20	20		73.20	58.56 S
	PIN PEDAL <i>new</i>	1.0 EA	10.20	20		10.20	8.16 S
	GEARCHANGE LEVER ? <i>new</i>	1.0 EA	102.60	20		102.60	82.08 S
	RUBBER PAD ? <i>new</i>	1.0 EA	3.40	20		3.40	2.72 S
	PLUG ? <i>new</i>	1.0 EA	3.80	20		3.80	3.04 S
	O-RING ? <i>new</i>	1.0 EA	0.40	20		0.40	0.32 S
	WASHER ? <i>new</i>	1.0 EA	1.30	20		1.30	1.04 S
	CIRCLIP E-TYPE ? <i>new</i>	1.0 EA	1.00	20		1.00	0.80 S
	FOOTREST PIN ? <i>new</i>	1.0 EA	9.90	20		9.90	7.92 S
	SPRING, FOOTRES ? <i>new</i>	1.0 EA	3.30	20		3.30	2.64 S
	LEFT FOOTREST <i>SCR</i>	1.0 EA	45.20	20		45.20	36.16 S
	FOOT PEG RUBBER ? <i>new</i>	1.0 EA	13.40	20		13.40	10.72 S
	LEFT FOOTREST <i>SCR</i>	1.0 EA	118.80	20		124.70	95.04 S
	REAR L.H. PLATE ? <i>new</i>	1.0 EA	96.60	20		101.40	77.28 S
	SPRING RETAINER ? <i>new</i>	1.0 EA	7.10	20		7.10	5.68 S
	SPRING ? <i>new</i>	1.0 EA	1.60	20		1.60	1.28 S
	BALL ? <i>new</i>	1.0 EA	0.60	20		0.60	0.48 S
	HEEL GUARD L.H. ? <i>new</i>	1.0 EA	38.70	20		40.60	30.96 S
	SCREW ? <i>new</i>	1.0 EA	1.10	20		1.10	0.88 S
	NUT, SELF-LOCKI ? <i>new</i>	1.0 EA	0.40	20		0.40	0.32 S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X

SERVICE ESTIMATE

109416 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Yap Bing Liang, Casper
Blk 109 Serangoon North Avenue 1
#04-651

Singapore 550109

Closed by : Michael Tan Yuh Ling
Svc Consultant : Michael Tan Yuh Ling
Remarks : Mr Yap Bing Liang, C

Inv.No. : D 0 Page 5
Inv.date : 21/02/2023
WIP No. : 61395
Veh. In/Out :
*Tel.No. : Mobile: 90297954
Reg.No. : FBT3612K / SCR
Reg.date : 25/01/2022
Mileage : 0
Chassis No. : ML05K00AAMT000169
Variant : SCR Desert Sled

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	FLASHER LIGHT	sur		1.0 EA	107.40	20	107.40	85.92	S
	FLASHER LIGHT	Xan		1.0 EA	107.40	20		85.92	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

2 days

P/P

23/02/23 @1640

Reby before rep

Labour Total 4,120.01
Parts Total 3,504.72
Package Total 0.00

Amount 7,624.73
Amount 7,624.73
GST @ 8 % 609.98
Total Amount 8,234.70
Less Amt Paid 0.00
Nett Amount 8,234.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Service Estimates are valid for 10 days from the above date.

This is a computer generated invoice, no signature is required.