

REPAIR ESTIMATE*

VEHICLE NO SHC8288Z
MAKE REG 08.01.2021
MODEL : HYUNDAI IONIQ G3

DATE 17.02.2023

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR WING MIRROR RH	Family well		\$1,391.70
	SUB TOTAL			\$1,391.70
	LESS 20%			\$278.34
	DISCOUNTED TOTAL			\$1,113.36
				\$-
	Labour Charge			\$300.00
	Panel Beating			\$300.00
	Spray Painting Charge			\$600.00
	TOTAL LABOUR			\$1,713.36
	ESTIMATE TOTAL			\$1,713.36

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged parts during survey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modifications are allowed
 - Supplementary charges must be pre-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

\$1413.36
282.67
T = 1130
21150

1 days L/S
20/2/23 3pm
18m