

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/CTI22002052/Tqp3-1							
	CHINA TAIPING INSURANCE (S) PTE LTD		R	Ref:	C35/CTI2200)2032/Tqy 3	
	3 ANSON ROAD # SPRINGLEAF TO\	16-00 VERSINGAPORE 079909	D	ate:	-07/00/2022-	22/02/2023	
				Code:			
1.	Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SME 8415D	Veh. Inspected		SMN 5955J		
	Policy No.	DMPCSNW00136252100	Coverage (\$)		0.00		
	Claim No.	SNM22D201553/C02/SME8415 D/LEWLC	Excess (\$)		0.00		
	Assign From	JENNY LEW	Assign Date	•	07/00/2022	22/02/2023	
2. Vehicle Particulars & Condition							
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	Steering					
	Brakes		Modification				
	General						
3.	3. Conditions of Tyres						
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
4.	Description of Damages						
5.	General Information						
	Accident Date	04/03/2022	Inspection Date		07/03/2022		
	Survey held at	ey held at GARAGE 13 PTE LTD					
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						