

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

days

Res.: _____

Yes or No

Lum Sum: _____

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

During survey vehicle already dismantled because AGI surveyor survey and ask them to dismantle.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	353Z
Vehicle Details	
Vehicle No.:	SMK5617H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	JA27 1.3 CVT
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	L13B14100904
Chassis No.:	J18MCK3850KS213723
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,727.00
Original Registration Date:	15 Apr 2019
First Registration Date:	15 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$5,727.00 2863
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2029
PARF Rebate Amount:	\$4,295.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,170.00
COE Rebate Amount:	\$16,049.00
Total Rebate Amount:	\$20,344.00

The information contained herein is correct as at 27 Feb 2023

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Look Photos. Zoom In : Extremely Beautiful. The Best.



Travel Overseas Offer: Park
Basement Shelter. Look Photos.
Extremely Beautiful.
Direct Owner Star Art

PRIME MOTOR & LEASING
PRIME MOTOR & LEASING PTE. LTD. GROUP OF COMPANIES
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Sort by 20 results/page

13 vehicles



Honda Jazz

Any Category

Advanced Search



Search

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Honda Jazz		Any	Any	2019	Any	Any	Any	Available

**Honda Jazz 1.5A RS**

\$86,800

\$12,610 /yr

13-May-2019

1,498 cc

59,120 km

Hatchback

Available

Immediate transfer of ownership upon collection. 1 owner. New facelifted Jazz 1.5 RS model. Very low mileage done. Fully serviced by K...

Guan Motor Pte Ltd

Posted: 27-Feb-2023

PREMIUM AD

**Honda Jazz 1.3A**

\$85,800

\$12,260 /yr

02-Dec-2019

1,318 cc

120,399 km

Hatchback

Available

One owner only! Very good condition. Like new vehicle. Agent unit. Full loan available. Call now to arrange viewing.

Think One Automobile & Trading

Posted: 26-Feb-2023

**Honda Jazz 1.3A**

\$75,800

\$11,820 /yr

29-Apr-2019

1,318 cc

38,000 km

Hatchback

Available

Immaculate condition, well maintained by careful owner. Flexible finance with the lowest interest rates to cater to your different needs. S...

✓ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

Car Empire Automobiles Pte Ltd

Posted: 25-Feb-2023

BuySafe

**Honda Jazz 1.3A (OPC)**

\$65,800

\$10,100 /yr

23-May-2019

1,318 cc

72,529 km

Hatchback

Available

1 Careful owner unit! Pristine condition from interior to exterior. 6 months 1 free servicing by reputable workshop with 25 years experien...

Posted: 25-Feb-2023

**Selling your Honda Fit?**

Receive \$3,000 more than trade-in when you sell your Honda Fit with Quotz.

Get Free Valuation with sgCarMart Quotz.

**Honda Jazz 1.3A (OPC)**

\$64,800

\$9,690 /yr

03-Sep-2019

1,318 cc

6,000 km

Hatchback

Available

Extremely low mileage. 1 owner. Warranty and maintenance fully maintained at Kah Motor. Servicing records available. Can convert to no...

Posted: 22-Feb-2023

PREMIUM AD

**Honda Jazz 1.5A RS**

\$90,800

\$12,890 /yr

18-Jul-2019

1,498 cc

29,857 km

Hatchback

Available

The Honda Jazz 1.5 RS is here to prove compact can be comfortable. Steady acceleration, improved suspension for a rhythmic drive. Bo...

SWheels Auto Pte Ltd

Posted: 11-Feb-2023

**Honda Jazz 1.3A**

\$72,800

\$11,320 /yr

03-May-2019

1,318 cc

48,332 km

Hatchback

Available

Full agent maintain, still under agent warranty till May 2024 and \$1500 agent servicing package balance to be pass to the new owner. Lo...

Posted: 04-Feb-2023

Compare



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT23000583	Page	1
	300 BEACH ROAD #17-04/07	Date	: 27. Feb 2023		
	THE CONCOURSE	Customer No.	: WZL009		
	SINGAPORE 199555	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMK5617B	Engine No	: L13B14100904		
Chassis No	: JHMGK3850KS213723	Date Time	: 27. Feb 2023 8:31:43 AM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: TEO CHIN CHOON, BERNARD	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/2/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TEO CHIN CHOON, BERNARD						
	OWNER INSURER: BUDGET DIRECT INSURANCE						
	ACC DATE: 27/02/2023						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: YP430L						
73211-T5A-J01	GLASS SETRR.WINDSHIELD <i>shothead</i>	1	625.60	25	469.20	37.54	506.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>neu</i>	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>neu</i>	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5 <i>neu</i>	1	9.10	25	6.82	0.55	7.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	2	60.00		120.00	9.60	129.60
68100-T5A-U10ZZ	TAIL GATE COMP <i>subsid</i>	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	5.54	74.76
74801-T5S-K01	LOCK ASSY, TAILGATE	1	91.10	25	68.32	5.47	73.79
04715-T5A-J50ZZ	FACE, RR.BUMPER <i>DIS</i>	1	496.90	25	372.67	29.81	402.48
91505-TM8-003	CLIP, BUMPER <i>neu</i>	7	2.30	25	12.07	0.97	13.04
71598-T5A-J50	SPACER, L.RR.BUMPER SIDE <i>Buy</i>	1	18.10	25	13.57	1.09	14.66
71593-T5A-J50	SPACER, R.RR.BUMPER SIDE <i>Buy</i>	1	18.10	25	13.57	1.09	14.66
71505-T5A-J50	GARNISH, RR.BUMPER <i>neu</i>	1	41.00	25	30.75	2.46	33.21
71507-T5A-J60	COVER, L.RR.BUMPER	1	22.10	25	16.57	1.33	17.90
71502-T5A-J60	COVER, R.RR.BUMPER <i>neu</i>	1	22.10	25	16.57	1.33	17.90
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>shothead</i>	1	320.00		320.00	25.60	345.60
84640-T5A-003ZA	LINING ASSY, RR.PANEL <i>17</i>	1	60.80	25	45.60	3.65	49.25
84651-TAR-Z03ZA	LINING ASSYL.TRUNK <i>17</i>	1	180.80	25	135.60	10.85	146.45
84601-TAR-Z03ZA	LINING ASSYR.TRUNK <i>17</i>	1	180.80	25	135.60	10.85	146.45

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK5617B
Chassis No : JHMGK3850KS213723
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : TEO CHIN CHOON, BERNARD
Ins Policy No. :
Date of Accident : 27/2/2023

Document No. : SQT23000583
Date : 27. Feb 2023
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : L13B14100904
Date | Time : 27. Feb 2023 8:31:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84521-T5A-901ZA	LID ASSYS SPARE TIRE <i>11</i>	1	203.10	25	152.32	12.19	164.51
84400-T5H-H02ZA	SHELF ASSY, RR. <i>11</i>	1	241.80	25	181.35	14.51	195.86
66100-TAR-T00ZZ	PANEL COMPR. <i>Body ID</i>	1	342.90	25	257.17	20.57	277.74
63320-T5A-900ZZ	GUTTER COMP, R, RR, PILLAR <i>Body ID</i>	1	94.90	25	71.17	5.69	76.86
04636-T5A-300ZZ	PANEL SET, R, RR, OUTSIDE <i>3uc</i>	1	610.70	25	458.02	36.64	494.66
73525-SYY-000	RUBBER RRR QTR W/SHIELD <i>1uc</i>	2	10.40	25	15.60	1.25	16.85
91501-T5A-901	CLIP A, QUARTER WINDSHIELD <i>1uc</i>	1	3.70	25	2.77	0.22	2.99
91502-T5A-901	CLIP B, QUARTER WINDSHIELD <i>1uc</i>	1	3.90	25	2.92	0.23	3.15
91503-TD4-003	CLIP C, QUARTER WINDSHIELD <i>1uc</i>	1	2.50	25	1.87	0.15	2.02
65540-T5A-N00ZZ	STIFFENER COMP, R, RR.	1	93.00	25	69.75	5.58	75.33
65612-T5A-300ZZ	FRAME BR, RR.	1	52.90	25	39.67	3.17	42.84
65619-T5A-300ZZ	FLANGE, RR, FRAME END	1	11.80	25	8.85	0.71	9.56
NMDVR-VUEROID-2C	DVR, VUEROID 2 CHANNEL <i>1uc</i>	1	343.93		343.93	27.51	371.44
Sum Item					4058.71	324.73	4383.44
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	24.00	324.00
Sum Ext. Service					300.00	24.00	324.00
BOSUN	SUNDRIES <i>1uc</i>	1	50.00		50.00	4.00	54.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	14.40	194.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	16.00	216.00
BOJSE	BODY JOINT SEALANT.	1	200.00		200.00	16.00	216.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	8.00	108.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	20.00	270.00
BG52D	REMOVE & INSTALL RR. R QTR GLASS. (N)	1	450.00		450.00	36.00	486.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	36.00	486.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	36.00	486.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	36.00	486.00

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK5617B
Chassis No : JHMGK3850KS213723
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : TEO CHIN CHOON, BERNARD
Ins Policy No :
Date of Accident : 27/2/2023

Document No. : SQT23000583
Date : 27. Feb 2023
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : L13B14100904
Date | Time : 27. Feb 2023 8:31:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BA10I	INSTALL IN-CAR DASHCAM	1	450.00	32.5	450.00	36.00	486.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	54.0	650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	✓	650.00	52.00	702.00
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	6800.00	45.0	6800.00	544.00	7344.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3200.00	31.0	3200.00	256.00	3456.00
				Sum Labor	14530.00	1,162.40	15,692.40

Survey By : Meray Lhu
Date & Time : 27/2/23 @ 2pm.
Excess :
Status : Not Authorised
Signature : Whaph. Sekupanty
12 - uplys.

Total Amount 18,888.71 1,511.13 20,399.84
Total (Inclusive of GST) 20,399.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023