

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

: SMK5617B

: 27/2/2023

Service and Body Repair

Tel: +65 6841 3838

Registration No

Chassis No

Owner's Name

Ins Policy No.

Date of Accident

Model

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT23000583

Page

Amount

incld GST

300 BEACH ROAD #17-04/07 THE CONCOURSE

: JAZZ 1.3LXR CVT 19YM (EURO 6)

; TEO CHIN CHOON, BERNARD

: LONPAC INSURANCE BHD

SINGAPORE 199555

: JHMGK3850KS213723

Customer No.

: 27. Feb 2023 : WZL009

Date Svc Advisor

Qty

: RUEBEN THOMAS

Engine No

: L13B14100904

Date | Time

: 27. Feb 2023 8:31:43 AM

Amount

8% GST

Amount

Surveyor Name

Survey Date

Authorisation Date

Unit Price Disc %

Item

Description TP DIRECT SETTLEMENT (J/NO:)

OWNER: TEO CHIN CHOON, BERNARD

OWNER INSURER: BUDGET DIRECT INSURANCE

ACC DATE: 27/02/2023

SURVEYED BY:

DATE:

REF NO:

TP INSURER: LONPAC INSURANCE

	TP VEH: YP430L						
73211-T5A-J01	GLASS SETRR.WINDSHIELD	1	625.60	25	469.20	37.54	506.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.55	7.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	9.60	129.60
68100-T5A-U10ZZ	TAIL GATE COMP	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	5.54	74.76
74801-T5S-K01	LOCK ASSY, TAILGATE	1	91.10	25	68.32	5.47	73.79
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	496.90	25	372.67	29.81	402.48
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.97	13.04
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
71505-T5A-J50	GARNISH,RR.BUMPER	1	41.00	25	30.75	2.46	33.21
71507-T5A-J60	COVER,L.RR.BUMPER	1	22.10	25	16.57	1.33	17.90
71502-T5A-J60	COVER,R.RR.BUMPER	1	22.10	25	16.57	1.33	17.90
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	25.60	345.60
84640-T5A-003ZA	LINING ASSY,RR.PANEL	1	60.80	25	45.60	3.65	49.25
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	180.80	25	135.60	10.85	146.45
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	180.80	25	135.60	10.85	146.45

Printed on 27/2/2023 11:03:12 AM

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT23000583

Page

2

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

300 BEACH ROAD #17-04/07 THE CONCOURSE

: JAZZ 1.3LXR CVT 19YM (EURO 6)

: TEO CHIN CHOON, BERNARD

: LONPAC INSURANCE BHD

SINGAPORE 199555

: JHMGK3850KS213723

Svc Advisor

: 27. Feb 2023

Customer No.

: WZL009

Date

: RUEBEN THOMAS

Engine No

: L13B14100904

Date | Time

Surveyor Name

: 27. Feb 2023 8:31:43 AM

Survey Date

Authorisation Date

Ins Policy No.

Registration No

Owner's Name

Chassis No

Model

: SMK5617B

Date of Accident : 27/2/2023

ltem	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	203.10	25	152.32	12.19	164.51
84400-T5H-H02ZA	SHELF ASSY,RR.	1	241.80	25	181.35	14.51	195.86
66100-TAR-T00ZZ	PANEL COMPRR.	1	342.90	25	257.17	20.57	277.74
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	94.90	25	71.17	5.69	76.86
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE	1	610.70	25	458.02	36.64	494.66
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	10.40	25	15.60	1.25	16.85
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.70	25	2.77	0.22	2.99
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.90	25	2.92	0.23	3.15
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.50	25	1.87	0.15	2.02
65540-T5A-N00ZZ	STIFFENER COMP,R.RR.	1	93.00	25	69.75	5.58	75.33
65612-T5A-300ZZ	FRAME BR.RR.	1	52.90	25	39.67	3.17	42.84
65619-T5A-300ZZ	FLANGE,RR.FRAME END	1	11.80	25	8.85	0.71	9.56
NMDVR-VUEROID-2C	DVR, VUEROID 2 CHANNEL	1	343.93		343.93	27.51	371.44
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	ì	300.00	Sum Item	300.00 300.00	24.00 24.00	324.00 324.00
BOSUN	SUNDRIES	1	50.00		50.00	4.00	54.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	14.40	194.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	16.00	216.00
BOJSE	BODY JOINT SEALANT.	1	200.00		200.00	16.00	216.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	8.00	108.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	20.00	270.00
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	450.00		450.00	36.00	486.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	36.00	486.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	36.00	486.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	36.00	486.00

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages,

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT23000583

Page

3

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE

Customer No.

: 27. Feb 2023 : WZL009

SINGAPORE 199555

Svc Advisor

: RUEBEN THOMAS

Registration No

: SMK5617B

Engine No

: L13B14100904

Chassis No Model

Customer

: JHMGK3850KS213723

Date | Time **Surveyor Name**

Date

: 27. Feb 2023 8:31:43 AM

Owner's Name

: JAZZ 1.3LXR CVT 19YM (EURO 6) From the thin the things are the things and the things are the thi

Survey Date

Authorisation Date

Ins Policy No. Date of Accident

: 27/2/2023

Item	Description	Qty	Unit Price Disc %	Amount	8% GST Amount	Amount incld GST
BA10I	INSTALL IN-CAR DASHCAM	1	450,00	450.00	36,00	486.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	650.00	52.00	702.00
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	6800.00	6800.00	544.00	7344.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	8. 1	3200.00	3200.00	256.00	3456.00
			Sum Labor	14530.00	1,162.40	15,692.40
Survey By	V					· · · · · · · · · · · · · · · · · · ·
Date & Time			Total Amount	18,888.71	1,511.13	20,399.84
Excess			Total (Inclusive of GST)			20,399.84
Status						
Signature	:					

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s),

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000,00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 27/02/2023 09:05 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 27/02/2023 07:10 (SGT) **Exact Location of Accident** Near 40 Owen Rd, Singapore 218862 Additional Location Information CTE TOWARDS AYE AFTER EXIT 7A Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK5617B

INSURED/POLICYHOLDER

Is company? Νo Name Of Registered Owner TEO CHIN CHOON, BERNARD NRIC No SXXXX353Z **Email Address** bt.prod@outlook.com Mobile Phone No (Phone) +65-96932439 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Transmission

CC

Honda Model Jazz Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited. Policy Number / Cover Note Number P10717060R00

Auto

1300

DRIVER

Name of Driver TEO CHIN CHOON, BERNARD NRIC No SXXXX353Z Date Of Birth 30/03/1988 Occupation Indoor

Date Of Driving Pass 12/08/2009 Driving experience 13 YEARS AND 6 MONTHS Gender Male Mobile Number (Phone) +65-96932439 Alt. Phone Number Email Address bt.prod@outlook.com Address **BLK 229 TAMPINES STREET 23** Address complement #09-271 Postcode 521229 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED STATEMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number YP430L Vehicle Manufacturer Isuzu Vehicle Model Vehicle Variant

White

Commercial vehicle

LAW HONG HOU

SXXXX826J

Vehicle Colour

NRIC No

Vehicle Category

Name of Driver

Contact Number	(Phone) +65-97437886
Address	-
Address complement	<u>=</u>
Postcode	-
Insurance Company Name	Lonpac Insurance Bhd
Nature Of Damage	-
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number Vehicle Manufacturer Vehicle Model	XB8308R Mitsubishi
	-
Vehicle Variant	-
Vehicle Colour	<u>u</u>
Vehicle Category	Commercial vehicle
Name of Driver	*
Contact Number	×
Address	5
Address complement	
Postcode	#
Insurance Company Name	
Nature Of Damage	566
Details of property damaged in accident	196
No. Of Passenger (Including Driver)	(%)

Vélucle

Namper ZWK 2013 B

SECTOMPIAN

IMPORTANT NOTICE

- 1. These report correctly the details of the accident to speed up the claims process
- 2. This Four must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any valid inacepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to
 copies at the report being imate available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA). Funderstand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapure ["GIA"] may/are permitted to collect, use, disclose and/or process my personal (lata/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law forms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to nie, which could involve disclosure of certain personal data about me to bring allow delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (h) all incurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, discluse and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service previders or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (a) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

12-Feb-2022

Oriver's Signature (if driver is not the policyholder). Date & Time: Reporting Centre Personnel's Signature Name:


NEIG/FIN No.:

0838

1

Vehicle Number: SMK 5617 B

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/2/2023 at about 7. Loan, I was driving
Glong CIE heading towards AYE. After exit 7A, the Fraftic
was slow moving and there was a verice break down on
the extreme left (are my utrick care to a complete
stop on lane 3. A few moments later, I felt a great
a corry yo 430 L has consider into my car and noticed
a lorry 19 430 L has consided into my car and there
was another lorry XB 8308 R which collided into the rear
84 YP 430 C.

IFWe decrate the foregoing particulars are true in every respect.

Date & Times

Driver's Signature (if driver is not the policyholder) Date & Time:

57-705-7021

0838

Reporting Costre Pensaned's Signature Nemer

NRIC/FIN No.:

5